

August 13, 2024

Attn: Zoltan Schafer, RPF
MaMook Natural Resources
Zoltan.schafer@ufn.ca

Subject: Road Deactivation and Reactivation Assessment: Stewardson Camp Road Network

Onsite File #: 988-5-4
EGBC PERMIT TO PRACTICE: 1002678

At the request of MaMook Natural Resources (MaMook), Onsite Engineering Ltd. (OEL), including Jaime Eggers, P.Geo., Jon Kroon, P.Geo., Richard Norman, P.Geo., Tim Wickman, P.Geo., Luke Wagner, GIT, Liam Giblin, GIT, Aidan Hoffman, and Allison Stubbs carried out road deactivation and upgrade assessments across the Stewardson Camp Road Network that runs from Hot Springs Cove to Mooyah Bay, on the west coast of Vancouver Island. The assessments were completed on June 10 to 14, July 1 to 5, and July 15 to 19 2024. As outlined in the Blackwell review of the TFL54 Roads, all Short-term roads (branch and spur roads) were assessed for permanent deactivation. Long-Term roads including Hot Springs Mainline, Satchie Mainline, Stewardson Mainline, HE780 (0+000 – 0+625), HE600 (0+000 – 0+530), and HE610 (0+000 – 0+280 m) were assessed for reactivation and maintenance concerns. A rockfall assessment was completed on Zuciarte Mainline, that connects Stewardson Mainline to Mooyah Bay on the north side of the Escalante River.

The assessments were carried out to reduce the liabilities associated with the roads held within the TFL54 road permit during the transfer to conservancy. The assessments evaluated the existing stability conditions of the roads, and effective road deactivation and maintenance/reactivation prescriptions were developed. Road deactivation and reactivation recommendations for Short-Term Roads are provided in **Appendices A and B**. Road reactivation recommendations for Long-Term Roads are provided in **Appendices C, D, and E**. The Zuciarte rock slope failure and rockfall assessment is detailed in **Appendix F**.

Roads not listed as active roads, i.e., not considered to be part of the road permit, were excluded from the assessment. One exception to this was made at the start of North Escalante Main where an inactive road parallels the mainline. Due to the potential for drainage from North Escalante Main to disrupt the lower road, it was assessed concurrently and drainage management recommendations were applied where required. The remaining “inactive roads” are outside of the project scope and are not included in this report. Roads included in the assessment are listed in **Table 1**.

Deactivation works as prescribed in this report are provided in a manner consistent with the “Best Management Practices Handbook, Hillslope Restoration in British Columbia” (BC Ministry of Forests, 2001). Adherence to recommendations provided will reduce the hazard of landslides initiating due to road instabilities. Expect the landslide hazard to become closer to the natural hazard levels for the area slopes.

Conditions at the time of the assessments were variable with mild temperatures, sun and rain and moderate surface flows in June. Conditions in July were warm to hot and sunny with low surface flows.

1.0 OBJECTIVES

The objective is to permanently deactivate the Short-Term roads to restore natural hillslope drainage paths, reduce slope instability, and enhance site productivity (where safe and practical and where access is no longer needed). As discussed below, the prescriptions to attain these objectives were marked directly in the field as well as documented in this report.

2.0 BACKGROUND


The roads extend from Hot Springs Cove in the south, to Mooyah Bay in the north and can be accessed centrally from Stewardson Camp, at the head of Stewardson Inlet. Stewardson Camp is located 6 km northwest of Hot Springs Village and 42 km northwest of Tofino, BC (Figure 1).

Road construction began in the late 1960's from Stewardson Camp, heading north towards Escalante River. The mainline and its spurs, including Satchie Mainline, had been constructed to just beyond the Escalante River crossing by the late 1970's and by the early 1980's Stewardson Mainline and Zuciarie Mainline were constructed allowing access to Mooyah Bay. North Escalante Main was also constructed in the early 1980's. Hot Springs Mainline was not constructed until sometime in the late 1990's to early 2000's. Most roads within the study area were built using pre-Code methods but information of exact construction methods or year of construction was not available for this assessment.

A road deactivation program was completed in the area in the late 1990's through Forest Renewal BC (FRBC). Many roads were deactivated during this time and have since been removed from the active road permit. Several roads that were listed as short-term roads on the provided maps had already been deactivated at the time of OEL's field assessments. Roads deemed to be deactivated or not requiring any works are listed in Table 1.

Resources at risk across the study area include site productivity and fish resources. Fish bearing reaches are located throughout the study area and were determined based on identification points on HabitatWizard paired with existing LiDAR data. In general, fish reaches extend to the toe of the slope and occur within Kanim Lake, Hesquiaht Point Creek, Satchie Creek, Hesquiaht Lake, Rae Lake, numerous unnamed "residual" streams that drain directly into Hesquiaht Harbour, and Escalante River and its tributaries.

Impact to fish reaches is most likely to occur at failed stream crossings, such as collapsed woodboxes or bridges, plugged culverts, or other sites of drainage disruption but may also occur through fill slope failures.



3.0 WORK CARRIED OUT

A high-level helicopter fly over of the study area was completed by Jaime Eggers and Marty Locker on March 21st, 2024. The fly-over was completed to narrow down the “on-ground” assessment areas. Where it was clear that drainage structures (culverts, woodboxes, bridges) had been pulled, cross-ditches had been installed, and pullback or recontouring of the road surface had been carried out, the road was deemed to be deactivated and no further action was taken. If the level of deactivation was either unclear or not deactivated, the road was assessed in the field. Roads deemed to be deactivated in the field and during the fly-over assessment are noted in Table 1 below.

During the field assessments, stability conditions were inferred from observed conditions of the road, such as existing landslides, tension cracks, road drainage conditions and existing drainage structures, the amount and composition of the road fill and the stability conditions downslope and in proximal terrain. In the field, pink flagging marks stations and prescriptions along the road. These field markings correspond directly to those in **Appendix A**.

The deactivation tables should be used to re-establish the field markings if necessary. **The site supervisor must verify, and where necessary replace, the field marks immediately before starting deactivation.**

4.0 SHORT TERM ROADS

It is understood the information contained in the *Best Management Practices Handbook: Hillslope Restoration in British Columbia* will be used as the standard when carrying out the work contained in the prescriptions. Failing to follow these standard operating procedures will result in inadequate pullback and potentially unsafe working situations for the excavator operator as well as the potential for future fill slope failures.

4.1 Existing Conditions

The existing stability hazard and resulting likelihood of spatial impact to fish resources for the Short-Term roads are outlined below in Table 1. Spatial impact to fish resources is rated based on the occurrence of stream crossings along the roads. If there are no stream crossings and no streams mapped in proximity, the spatial impact is rated as low; if there are stream crossings through fish habitat, the likelihood of spatial impact is rated as high; if the road is located in close proximity to fish reaches but does not cross any streams, the likelihood of spatial impact is rated as moderate. Roads are listed in rough order from south to north through the study area.

Table 1: Short Term Roads: Hazard and Likelihood of Spatial Impact

| Road | Start Stn. | End Sta. | Stability Hazard | Likelihood of Spatial Impact to Fish Reaches | Deactivation Level, Comments |
|-----------------------|---|----------|------------------|--|------------------------------|
| HS 7.8 | Deactivation completed, no works required | | | | |
| HS 7.0 | Deactivation completed, no works required | | | | |
| HS 6.7 | - | - | Low | Low | Permanent |
| BR2080, BR2070 | No work deemed necessary | | | | |
| BR2061, BR2060 | - | - | Low | Low | Permanent |
| HS 4.3, HS 4.3A | Deactivation completed, no works required | | | | |
| BR2050 | No work deemed necessary | | | | |
| BR2031, HS3.5, BR2030 | - | - | Low | Moderate | Permanent |
| BR2020, BR2031 | Deactivation completed, no works required | | | | |
| BR2010 | No work deemed necessary | | | | |
| K1020 | Deactivation completed, no works required | | | | |
| K1010 | - | - | Low | Moderate | Permanent |
| K1000 | - | - | Low | Moderate | Permanent |
| Kanim Main | Road does not exist, no action required | | | | |
| H1000 | JK101 | JK117 | Low | Moderate | Permanent |
| | JK118 | JK119 | Moderate | Moderate | |
| | JK122 | JK125 | High | Moderate | |
| | JK131 | JK132 | Moderate | Moderate | |
| H520 | No work deemed necessary | | | | |
| HS50 | JK72 | JK79 | Low | Low | Permanent |
| | JK79 | JK80 | High | Low | |
| | JK80 | JK82 | Moderate | Low | |
| | JK82 | JK84 | Moderate | Moderate | |
| HS100 | No work deemed necessary | | | | |
| HS200 | JK194 | JK192 | Low | Moderate | Permanent |
| | JK192 | JK190 | High | Moderate | |
| | JK190 | JK179 | Moderate | Moderate | |
| | JK179 | JK178 | High | Moderate | |
| | JK178 | JK167 | Moderate | Moderate | |
| HS240 | JK166 | JK151 | Moderate | Low | Permanent |
| | JK151 | JK150 | Moderate | Low | |
| | JK150 | JK137 | Moderate | Moderate | |
| HS246, HS243 | No work deemed necessary | | | | |
| HS300 | - | - | Low | Low | Permanent |
| HS310 | - | - | Low | Low | Permanent |
| HS300-OEL-A | - | - | Low | Low | Permanent |

| | | | | | |
|---|--|-------|----------|----------|-----------|
| HS311, HS311-1, HS311-2 | JK198 | JK200 | Moderate | Low | Permanent |
| | JK200 | JK208 | Low | Low | |
| | JK208 | JK209 | Low | Low | |
| | JK209 | JK211 | Moderate | Low | |
| HS310 | - | - | Low | Low | Permanent |
| STE502-1 | Deactivation completed, no works required | | | | |
| H10A, H10R | - | - | Moderate | High | Permanent |
| HE785, HE789, HE786, HE787, HE788 | No work deemed necessary | | | | |
| H220, H221 | Road not built, no works required | | | | |
| HE600, HE605 | No action required | | | | |
| HE610 | - | - | Low | Low | Permanent |
| HE610A | Deactivation completed, no works required | | | | |
| H710 | - | - | Low | Low | Permanent |
| H770, H790, H770-OEL-A | - | - | Low | Low | Permanent |
| H771 | No work deemed necessary | | | | |
| H760 | No work deemed necessary | | | | |
| H4000 (R07675), H1500 | Road does not exist, no action required | | | | |
| H4000 (R13813), H1500 | Deactivation completed, no works required | | | | |
| H4100 | Deactivation completed, no works required | | | | |
| H1610 | - | - | Low | Moderate | Permanent |
| H1615 | No work deemed necessary, no drainage concerns | | | | |
| H1625 | No work deemed necessary, no drainage concerns | | | | |
| H1620 | - | - | Low | Moderate | Permanent |
| H1600 | - | - | Low | Moderate | Permanent |
| H1645 | - | - | Low | Moderate | Permanent |
| H1640 | - | - | Low | Moderate | Permanent |
| H1650 | - | - | Low | Moderate | Permanent |
| H1660 | No work deemed necessary, no drainage concerns | | | | |
| H1670 | - | - | Low | Low | Permanent |
| H1680 | - | - | Low | Moderate | Permanent |
| H103, H105, H107, H1110 | Deactivation completed, no works required | | | | |
| H1080 | - | - | Low | Low | Permanent |
| HE1081 | - | - | Low | Low | Permanent |
| HE1085 | - | - | Low | Low | Permanent |
| HE1083, HE1087 | Deactivation completed, no works required | | | | |
| H800 | Deactivation completed, no works required | | | | |
| 500 | - | - | Low | Moderate | Permanent |
| 512 | - | - | Low | High | Permanent |
| 510, 522, 524, 514 | No work deemed necessary, no drainage concerns | | | | |

| | | | | | |
|------------------------|---|---|------|----------|-----------|
| 520 | - | - | Low | Moderate | Permanent |
| 530 | - | - | Low | Moderate | Permanent |
| 550 | - | - | Low | Moderate | Permanent |
| H5600 | - | - | Low | Moderate | Permanent |
| H5700 | - | - | Low | Moderate | Permanent |
| BR5900 | - | - | Low | High | Permanent |
| H4610 | Deactivation completed, no works required | | | | |
| BR6000, BR6010 | - | - | Low | High | Permanent |
| BR6200 | - | - | Low | High | Permanent |
| BR6220, BR6240 | Deactivation completed, no works required | | | | |
| H6280 | Deactivation completed, no works required | | | | |
| BR6300 | - | - | Low | High | Permanent |
| BR6301 | - | - | Low | Moderate | Permanent |
| E19 | Deactivation completed, no works required | | | | |
| North Escalante | - | - | High | Moderate | Permanent |
| E510 | - | - | High | Moderate | Permanent |
| B110, BR100 | Deactivation completed, no works required | | | | |
| Z1900, Z1901, Z1902 | - | - | Low | High | Permanent |

4.2 Deactivation

Culvert removal and cross ditching is required along many sections of the roads to reestablish the natural drainage patterns. All corrugated metal pipes (CMPs), wood box culverts (WBCs) and corrugated plastic pipes (CPPs) should be removed from the site and scheduled for recycling.

Road fill pullback is recommended along some sections to stabilize the roads for the long term. The length of pullback is indicated in the prescriptions (i.e. light (P3), moderate (P6), heavy (P9), and heavy+ (P12)) as an estimate of slope distance from the crest of the fill slope/edge of the road (Figure 1a). Additional pullback may be needed at some locations if more road fill is present than evident from the visual inspection during the work.

Pullback Prescriptions

Light pullback – Tension cracks and settling on outer 1-2 m of road, windrows or large berms present; likely only a thin wedge of fill material present. Remove side cast material built up on the outside shoulder. All side cast with the potential to start a landslide must be retrieved. (Figure 1b).

Moderate pullback (discretionary) – Failing fill slope, tension cracks and settling on outer +2m of road; likely a thicker wedge of fill. Comb fill slope material back to original ground surface or until coarse and rocky material remains. **The objective is to comb-back the fill, ensuring that there is no lip remaining at the toe of the pullback.** This may require all fill material to be pulled back. All side cast with the potential to start a landslide must be retrieved.

Heavy pullback (full) – In thick fills where entire fill slope is or may become unstable and large tension cracks or fill slope failures are present or starting to fail, pull back fill slope material to original ground. All

side cast with the potential to start a landslide must be retrieved. Where full (heavy+) pullback is prescribed and where safety permits, benching downslope to retrieve all fill material may be required.

All fill should be placed along the inside edge of the road, removing the ditch line completely.




Figure 1: Typical pullback methods (1999 FRBC, Technical Standards and Guidelines for Road Deactivation/Restoration Activities)

4.3 Reactivation of short-term roads (by request)

Branch HE780 is a short-term road that branches off Stewardson Mainline at 5.3 km. It was selected for reactivation by Ahousht Nation for future use within the conservancy. The road and its spurs were not assessed beyond the mapped junction with branch H220 due to the level of forest regeneration. Conifers growing on HE780 are estimated to be more than 20-years old beyond the 7 m all-steel portable bridge at JE6.

A landslide initiated from HE780 near the junction with HE786 during a storm event in 2017. The slide is 230 m long by 15 m wide and terminated onto gentle gradient terrain over 400 m upslope of Stewardson Mainline. Very minor fines may have been transported to the ocean. To deactivate the back end of the road network, conifer removal is required and the road crossing at the slide requires repairs. Disturbance associated with reactivation and deactivation works would set the natural recovery of the road back several decades. Due to the gentle terrain located between the roads and elements at risk (Stewardson Mainline, fish habitat) it was deemed best to leave the road to continue recovering naturally. H220 was also requested to be retained for future use. However, this road and its spur H220A were never constructed. Reactivation recommendations for HE780 are included in **Appendix B**.

Roads HE600 and HE610 that branch off Stewardson Mainline just past 8 km were also selected to be retained for future use within the conservancy by Ahousaht Nation. Reactivation recommendations for these roads are included in **Appendix B**.

4.4 Reconstruction (for access)

One short term road requires reactivation to gain access to the back end of the work area.

Z1900 (0.4 Km): Bridge has been washed away > survey completed; draft designs underway by OEL.

Bridge inspections have been completed by OEL engineers along North Escalante Mainline and Br.500 and its spur roads. Bridge inspections are required along short-term roads prior to deactivation activities commence to ensure structures are safe for excavator, rock truck, and light vehicle access.

5.0 LONG TERM ROADS

5.1 Reactivation

Hot Springs Mainline, Satchie Mainline, Stewardson Mainline and Zuciarte Mainline are slated as long-term roads that will be retained for future use. Hot Springs Mainline, Satchie Mainline, and Stewardson Mainline from 0 Km to the Escalante Bridge at 34.4 Km were assessed for reactivation and are included in this report and the attached maps. Stewardson mainline was assessed beyond the bridge at 34.4 km by helicopter only for any glaring road concerns due to its location on gentle benched terrain. Culverts along this portion of the mainline will be picked up and catalogued during P.Eng. bridge inspections prior to road reactivation.

Several stream crossings along Stewardson Mainline were impacted during a storm event in 2017 and require significant repairs:

- 3.5 km debris flow > ford design completed by OEL
- 7.5 km bridge washed out > draft road realignment and bridge designs completed by OEL
- 15.9 km road washed out on woods side of woodbox > survey completed, draft designs underway by OEL
- 21.7 km debris flow has impacted bridge > survey completed, draft designs underway by OEL
- 22.2 km debris flow has impacted bridge > survey completed, draft designs underway by OEL

Zuciarte Mainline was assessed by air by Jon Kroon, P.Geo. on June 11th, 2024. Several areas with loose boulders and one significant rockfall zone at 5 Km were observed. An on-ground inspection of the 5 Km rockfall was completed on July 17th, 2024, by Jon Kroon, P.Geo. and is detailed in an attached report (Appendix F). A safe work procedure is also included in **Appendix F**.

Reactivation recommendations for Hot Springs Mainline, Stewardson Mainline and Satchie Mainline are outlined in **Appendices C, D and E**, respectively.

Bridge inspections have been completed by OEL engineers along Hot Spring Mainline, several portions of Stewardson Mainline, and most of Satchie Mainline. Inspections will be completed prior to reactivation activities commence.

6.0 INSPECTIONS AND VERIFICATION

Senior personnel familiar with the deactivation techniques in the Best Management Practices Handbook should carry out inspections during the deactivation work and **a qualified registered professional should review the deactivation work prior to completion and sign off on the same** (Appendix 2 in Guidelines for Professional Services in the Forest Sector – Forest Roads, June 2012).

Wooden bridges along Short-Term Roads should be assessed by a qualified professional prior to use to ensure they are safe for use and to determine their load ratings.

In areas where road fill cannot be safely retrieved, and some residual hazard is expected to remain, an inspection by a qualified registered professional is prudent. The size and extent of such an area, as well as the downslope / downstream risks, are important considerations regarding the timing of the inspection. Smaller areas, or areas of lesser risk, can be inspected following completion of the work. For larger areas, or areas with high downslope / downstream risks, inspections concurrent with the work are recommended to address deficiencies in conjunction with full time supervision.

7.0 LIMITATIONS AND CLOSURE

These permanent deactivation prescriptions and reactivation recommendations are made based on a visual inspection of the Hot Springs Mainline, Satchie Mainline, and Stewardson Mainline road networks using the techniques described in the Best Management Practices Handbook. If site conditions change, or the prescriptions are not expected to meet the objectives discussed in this report, some on-site changes may be needed for the prescriptions. If any significant changes are required, contact a qualified registered professional with proven knowledge and experience in road deactivation and terrain stability assessment.

We trust this report outlines the requirements for deactivation and reactivation along the assessed roads. If you have any questions regarding this report, please contact our office at your convenience.

Respectfully submitted,
Onsite Engineering Ltd.

Prepared by: Allison Stubbs and Jaime Eggers, P.Ge.

Reviewed by: Tim Wickman, P.Ge.

Attached:

Appendix A: Road Deactivation Recommendations for Short-Term Roads
Appendix B: Road Reactivation Recommendations for Short-Term Roads
Appendix C: Road Reactivation Recommendations for Hot Springs Mainline
Appendix D: Road Reactivation Recommendations for Stewardson Mainline
Appendix E: Road Reactivation Recommendations for Satchie Mainline
Appendix F: Zuciarte 5.0 Km Rockfall Assessment & Work Safe Procedures

Road Deactivation and Reactivation Maps will be sent as separate packages due to file size.

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|----------------|---------|--------------------|--|
| HS7.8 | | | |
| Deact Map 1 | JK 2 | No recommendations | Road is deactivated with pulled CMPs and no fill issues |
| HS7.0 | | | |
| Deact Map 1 | JK 6 | No recommendations | Road is deactivated, creek down ditched is okay, flows through CKP at StewML, no need for XD at road start |
| HS6.7 | | | |
| Deact Map 1 | JK 7 | Add XD | Low point in road |
| BR2080 | | | |
| Deact Map 1 | JK 9 | No recommendations | Landing spur, no action |
| BR2070 | | | |
| Deact Map 1, 2 | JK 10 | No recommendations | Small spur, no action |
| BR2061 | | | |
| Deact Map 2 | JK 16 | No recommendations | Shallow XD here, captures water effectively, road heavy brush and trees, no action |
| Deact Map 2 | JK 17 | No recommendations | Ditch from both roads converge in sump, overflow would go belowditch below fill at switch, is all okay, not much water |
| BR2060 | | | |
| Deact Map 2 | JK 13 | Add XD | No flow in ditch here a little wet, heavily treed and over grown |
| Deact Map 2 | JK 14 | No recommendations | Existing XD |
| Deact Map 2 | JK 15 | Add XD | Light road erosion below on switch |
| Deact Map 2 | JK 18 | Add XD | Add XD to capture future XD water from above |
| Deact Map 2 | JK 19 | Add XD | Shallow low point |
| Deact Map 2 | JK 20 | Remove ditchblock | Ditchblock, not a good spot |
| Deact Map 2 | JK 21 | Enhance XD | Shallow XD, needs bigger and longer |
| BR2050 | | | |
| Deact Map 2 | JK 22 | No recommendations | Road on flats, no action |
| HS3.5 | | | |
| Deact Map 2, 3 | JK 26 | No recommendations | shallow XD, okay |
| Deact Map 2, 3 | JK 27 | No recommendations | creek is flowing well, looks debuilt beyond |
| BR2031 | | | |
| Deact Map 2, 3 | JK 25 | No recommendations | Existing XD, good but shallow |
| BR2030 | | | |
| Deact Map 2, 3 | JK 28 | No recommendations | Spur or end of rd has been deactivated with XD at start |
| Deact Map 2, 3 | JK 29 | Add XD | Steep grade, minor erosion |
| Deact Map 2, 3 | JK 30 | Add XD | Top of hill |
| BR2020 | | | |
| Deact Map 2, 3 | JK 31 | No recommendations | Spur is deactivated with XD at start |

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|-------------------|---------|--|--|
| BR2010 | | | |
| Deact Map 3 | JK 32 | No recommendations | Spur is landing, used for milling, okay to leave as is |
| K1020 | | | |
| Deact Map 3 | JK 35 | No recommendations | spur is deactivated |
| K1010 | | | |
| Deact Map 3 | JK 37 | No recommendations | road has no XDs but is okay, small quarry with water is okay |
| Deact Map 3 | JK 38 | Add XD | low point |
| K1000 | | | |
| Deact Map 3, 5 | JK 39 | Enhance XD | partial XD, at low point |
| Deact Map 3, 5 | JK 40 | Add XD | depression |
| Kanim Main | | | |
| Deact Map 3, 5 | JK 71 | No recommendations | no road, mature second growth |
| HS311 | | | |
| Deact Map 4 | JK 198 | Start MPB | steep fills above steep ground |
| Deact Map 4 | JK 199 | Pull back woody debris pile, remove waterbar | WB and LWD pile |
| Deact Map 4 | JK 200 | End MPB | |
| Deact Map 4 | JK 201 | Enhance XD | Existing low XD |
| Deact Map 4 | JK 202 | Enhance XD | Existing low XD |
| Deact Map 4 | JK 203 | Enhance XD | Existing low XD |
| Deact Map 4 | JK 204 | Enhance XD | Existing low XD |
| Deact Map 4 | JK 205 | Enhance XD | Existing low XD |
| Deact Map 4 | JK 206 | Enhance XD | Existing low XD |
| Deact Map 4 | JK 207 | Enhance XD | Existing low XD |
| Deact Map 4 | JK 208 | Start LPB | |
| Deact Map 4 | JK 209 | End LPB | |
| Deact Map 4 | JK 210 | Add XD | |
| Deact Map 4 | JK 211 | Add XD | |
| HS310 | | | |
| Deact Map 4 | JK 195 | Pull CMP, add XD | 1000 CMP, road is deactivated beyond this point |
| Deact Map 4 | JK 196 | Add XD | deep ditch with standing water |
| Deact Map 4 | JK 197 | Add XD | |
| Deact Map 4 | JK 212 | Pull CMP, add XD | Existing CMP |
| Deact Map 4 | JK 213 | Pull CMP, add XD | Existing 1000 CMP |
| Deact Map 4 | JK 214 | Add XD | |
| Deact Map 4 | JK 215 | Pull CMP, add XD | Existing CMP |
| Deact Map 4 | JK 216 | Pull CMP, add XD | Existing CMP |
| Deact Map 4 | JK 217 | Add XD | ponding ditch water, seep creek here |
| Deact Map 4 | JK 218 | Add XD | Ditch water |
| Deact Map 4 | JK 219 | Pull CMP, add XD | Existing CMP |

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|--------------------|---------|---|--|
| HS300-OEL-A | | | |
| Deact Map 4 | JK 220 | Pull CMP, add XD | CMP |
| HS300 | | | |
| Deact Map 3, 4 | JK 221 | Pull WBC | Existing WBC |
| Deact Map 3, 4, 5 | JK 222 | Pull WBC | Existing WBC |
| Deact Map 3, 4, 5 | JK 223 | Pull WBC | Existing WBC |
| Deact Map 4, 5 | JK 224 | Add XD | |
| HS240 | | | |
| Deact Map 4 | JK 166 | Pull CPP, add XD | landslide path, 1000 CPP |
| Deact Map 3, 4 | JK 165 | Pull CPP, add XD | 800 CPP |
| Deact Map 3, 4 | JK 164 | Add XD | steep grade, sberry site |
| Deact Map 3, 4 | JK 163 | Add XD | location stream should be? |
| Deact Map 3, 4 | JK 162 | Pull CPP, add XD | 1000 CPP |
| Deact Map 3, 4 | JK 161 | Pull WBC | shallow WB |
| Deact Map 3, 4 | JK 160 | Pull CPP, can leave XD or replace with fill | 1000 CPP |
| Deact Map 3, 4 | JK 159 | Add XD | Low point in road |
| Deact Map 3, 4 | JK 158 | Pull CPP, add XD | 1000 plastic pipe (CPP) |
| Deact Map 3, 4 | JK 156 | Add XD | |
| Deact Map 3, 4 | JK 154 | Pull CMP, add XD | 1000 CMP |
| Deact Map 3, 4 | JK 153 | Pull CMP, add XD | 800 CMP |
| Deact Map 3, 4 | JK 152 | Add XD | start of PB, seepage |
| Deact Map 3, 4 | JK 151 | Start HPB | natural stump in fiil, seep from cut |
| Deact Map 3, 4, 5 | JK 150 | End HPB | fills above steep, not really settling yet but steep below, a lot of Sberry |
| Deact Map 3, 4, 5 | JK 149 | No recommendations | Thick tills, high cut, ravelling and slumping on road, access failure fine too |
| Deact Map 3, 4, 5 | JK 148 | Add XD | 1000 CMP |
| Deact Map 3, 4, 5 | JK 147 | Pull CMP, add XD | 800 CMP |
| Deact Map 3, 4, 5 | JK 146 | Pull CMP, add XD | 800 CMP |
| Deact Map 3, 4, 5 | JK 145 | Pull CMP, add XD | 800 CMP |
| Deact Map 3, 4, 5 | JK 144 | Pull bridge | 7m log bridge |
| Deact Map 3, 4, 5 | JK 143 | Pull CMP, add XD | 800 CMP |
| Deact Map 3, 4, 5 | JK 142 | Pull WBC | WBC, with creek |
| Deact Map 4, 5 | JK 141 | Pull WBC | WBC, brushy rd right is HS240 |
| Deact Map 4, 5 | JK 140 | Add XD | start of hill, above quarry |
| Deact Map 4, 5 | JK 139 | Pull WBC | seep with WBC |
| Deact Map 4, 5 | JK 138 | Add XD | steep grade with road wash |
| Deact Map 4, 5 | JK 137 | Pull WBC | WBC |

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|----------------|---------|------------------------------|---|
| HS243 | | | |
| Deact Map 4, 5 | JK 157 | No recommendations | spur overland construction, no action |
| HS246 | | | |
| Deact Map 4, 5 | JK 155 | No recommendations | spur is fine, no action |
| HS200 | | | |
| Deact Map 4 | JK 194 | No recommendations | Large stream, XD good |
| Deact Map 4 | JK 193 | No recommendations | Existing XD |
| Deact Map 4 | JK 192 | Start HPB, preserve conifers | |
| Deact Map 4 | JK 191 | Enhance XD | existing XD, shallow, with water from ditch |
| Deact Map 4 | JK 189 | End HPB, preserve conifers | steep fills 8m to mature second growth |
| Deact Map 4 | JK 188 | Add XD | seep at landing |
| Deact Map 4 | JK 187 | Add XD | |
| Deact Map 4 | JK 186 | Pull CMP, add XD | possible WB or CMP |
| Deact Map 4 | JK 185 | Add XD | possible culvert |
| Deact Map 4 | JK 184 | Pull CMP, add XD | CMP |
| Deact Map 4 | JK 183 | Pull CMP, add XD | CMP |
| Deact Map 4 | JK 182 | Pull CMP, add XD | CMP |
| Deact Map 4 | JK 181 | Add XD | Top of hill |
| Deact Map 4 | JK 180 | Pull CMP, add XD | CMP |
| Deact Map 4 | JK 179 | Start HPB | |
| Deact Map 4 | JK 178 | End HPB | |
| Deact Map 4 | JK 177 | Add XD | Seep |
| Deact Map 4 | JK 176 | Pull CMP, add XD | Existing CMP |
| Deact Map 4 | JK 175 | Pull CMP, add XD | CMP |
| Deact Map 4 | JK 174 | Add XD | seep, water in ditch |
| Deact Map 4 | JK 173 | Pull CMP, add XD | 600 CMP |
| Deact Map 4 | JK 172 | Add XD | seepage |
| Deact Map 4 | JK 171 | Pull WBC | buried WBC |
| Deact Map 4 | JK 170 | Add XD | more seep, no culvert |
| Deact Map 4 | JK 169 | Add XD | continued seep from cuts, possible CMP buried |
| Deact Map 4, 5 | JK 168 | Add XD | seepage, no culvert |
| Deact Map 4, 5 | JK 167 | No recommendations | Existing XD good |
| HS50 | | | |
| Deact Map 4, 5 | JK 72 | Add XD | bottom of switch, ditchline fill below |
| Deact Map 4, 5 | JK 73 | Pull WBC | WBC |
| Deact Map 4, 5 | JK 74 | Add XD | |
| Deact Map 4, 5 | JK 75 | Pull WBC | WBC |
| Deact Map 4, 5 | JK 76 | Add WB | Road wash |
| Deact Map 4, 5 | JK 77 | Add WB | |
| Deact Map 4, 5 | JK 78 | Pull WBC | WBC |

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|-------------------|---------|---|--|
| Deact Map 4, 5 | JK 79 | Start HPB | rocky fill down to 45% slopes, rd in FB with SC of rock, might be difficult to retrieve, PB what is possible and preserve mature conifers where sensible |
| Deact Map 4, 5 | JK 80 | Pull WBC, end HPB, start MPB | |
| Deact Map 4, 5 | JK 81 | Add XD | double seepage from cut |
| Deact Map 4, 5 | JK 82 | End MPB, start HPB, preserve conifers | |
| Deact Map 4, 5 | JK 83 | Add XD, continue HPB, preserve conifers | WBC |
| Deact Map 4, 5 | JK 84 | End HPB | |
| Deact Map 3, 4, 5 | JK 85 | Pull WBC | WBC |
| Deact Map 3, 4, 5 | JK 86 | Pull WBC | WBC |
| Deact Map 3, 4, 5 | JK 87 | Pull bridge | 6m log bridge |
| Deact Map 3, 4, 5 | JK 88 | Add XD | Top of hill |
| Deact Map 3, 4, 5 | JK 90 | Add XD | bit of ditch water |
| Deact Map 3, 4, 5 | JK 91 | Pull WBC | WBC |
| Deact Map 3, 4, 5 | JK 92 | Add XD | downslope of quarry |
| Deact Map 3, 4, 5 | JK 93 | Pull WBC | WBC |
| Deact Map 3, 4, 5 | JK 94 | Add XD | road start, water in ditch |
| HS100 | | | |
| Deact Map 3, 4, 5 | JK 89 | No recommendations | No road |
| H1000 | | | |
| Deact Map 3, 4, 5 | JK 95 | Add XD | Seep onto road |
| Deact Map 3, 4, 5 | JK 96 | Pull WBC | Seepage from cut, WBC here |
| Deact Map 3, 4 | JK 97 | Pull WBC | Small creek 10m back, WBC here |
| Deact Map 3, 4 | JK 98 | Pull WBC | WBC |
| Deact Map 3, 4 | JK 99 | Add XD | Road wash |
| Deact Map 3, 4 | JK 101 | Pull WBC | Minor ditch water, WBC |
| Deact Map 3, 4 | JK 102 | Add XD | Small creek |
| Deact Map 3, 4 | JK 103 | Pull WBC | WBC |
| Deact Map 3, 4 | JK 104 | Add XD | Seep |
| Deact Map 3, 4 | JK 105 | Pull WBC | WBC |
| Deact Map 3, 4 | JK 106 | Pull bridge | 15m long log bridge |
| Deact Map 3, 4 | JK 107 | Add XD | Seep |
| Deact Map 3, 4 | JK 108 | Pull WBC | WBC |
| Deact Map 3, 4 | JK 109 | Add XD | Wet ditch, possible WBC |
| Deact Map 3, 4 | JK 110 | Pull WBC | WBC, no outlet |
| Deact Map 3, 4 | JK 111 | Add reverse WB, into ditch | Road wash on switch |
| Deact Map 3 | JK 112 | Add reverse XD off end of switch | More road wash down switch, flows around on road currently |
| Deact Map 3 | JK 113 | Pull WBC | Large WBC |

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|----------------|---------|---------------------------------|---|
| Deact Map 3 | JK 114 | Add XD | Small creek |
| Deact Map 3 | JK 115 | Pull WBC | Creek and WBC |
| Deact Map 3 | JK 116 | Add XD | Steep grade |
| Deact Map 3 | JK 117 | Pull bridge | 15m long log bridge |
| Deact Map 3 | JK 118 | Start HPB | Fill slope slump 5m below road, undercuts fill |
| Deact Map 3 | JK 119 | End HPB | Gully edge |
| Deact Map 3 | JK 120 | Add reverse XD, back into ditch | Road erosion, through cut so cant do normal XD |
| Deact Map 3 | JK 121 | Pull bridge | 15ish m long log bridge |
| Deact Map 3 | JK 122 | Start HPB | 9m HPB, 20m to bench |
| Deact Map 3 | JK 123 | Pull CMP, add XD | CMP, burried intake, downslope ditch mostly infilled with high till cuts |
| Deact Map 3 | JK 124 | Add XD | Water accumulating in ditch from multiple seepage, ditch now 1.2m deep |
| Deact Map 3 | JK 125 | End HPB | |
| Deact Map 3 | JK 126 | Add XD | |
| Deact Map 3 | JK 127 | Add XD | Steep grade |
| Deact Map 3 | JK 128 | Add XD | Ditch water |
| Deact Map 3, 5 | JK 129 | Pull CMP, add XD | CMP 500 |
| Deact Map 3, 5 | JK 130 | Add XD | Steep grade, no culvert |
| Deact Map 3, 5 | JK 131 | Start MPB | |
| Deact Map 3, 5 | JK 132 | End MPB | vet Cw below rd starts here |
| Deact Map 3, 5 | JK 133 | Add XD | |
| Deact Map 3, 5 | JK 134 | Add XD | |
| H520 | | | |
| Deact Map 3 | JK 100 | No recommendations | Existing big XD near start, has creek, mid road has tracks directing water across, beyond is only hoe trail, no surface |
| H10A | | | |
| Deact Map 5 | JK 55 | Add XD | Creek upslope, cant find CMP, water goes sub at road |
| Deact Map 5 | JK 56 | Add XD | Ditch water, probably where creek goes, security XD here |
| Deact Map 5 | JK 57 | Add XD | Steep slope starts here and below, but seep here with reverse WB, should cross rd here |
| Deact Map 5 | JK 58 | Pull CMP, add XD | CMP 1000 |
| Deact Map 5 | JK 59 | Add XD | Second seep, needs back up XD |
| Deact Map 5 | JK 60 | Add XD | |
| Deact Map 5 | JK 61 | Add XD | |
| Deact Map 5 | JK 62 | Pull CMP, add XD | Existing CMP |
| Deact Map 5 | JK 63 | Add XD | |

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|--------------|---------|--------------------|---|
| HE610 | | | |
| Deact Map 6 | JE 42 | Pull CMP add XD | No deact required beyond big bench no drainage issues well veg with alder |
| Deact Map 6 | JE 43 | Deepen existing XD | |
| Deact Map 6 | JE 44 | Deepen existing XD | |
| Deact Map 6 | JE 45 | Deepen existing XD | |
| Deact Map 6 | JE 46 | Pull CMP add XD | Existing CMP |
| Deact Map 6 | JE 47 | Deepen existing XD | |
| Deact Map 6 | JE 48 | Add XD | Several large holes in road no sign of cmp |
| Deact Map 6 | JE 49 | Pull CMP add XD | Existing CMP |
| HE600 | | | |
| Deact Map 6 | JE 41 | No recommendations | Spur is well vegetated and on bench no recs aside from xd ar jcn |
| HE605 | | | |
| Deact Map 6 | JE 40 | No recommendations | Road taken back by forest on bench no deact necessary |
| H771 | | | |
| Deact Map 7 | JE 100 | No recommendations | No road found |
| H790 | | | |
| Deact Map 7 | JE 97 | No recommendations | Alder up to 20 cm diameter dont bother doing anything |
| H770 | | | |
| Deact Map 7 | JE 98 | Pull CMP add XD | Could leave 800 CMP with little flow very brushy with 20 cm dr to here. Can see end of road |
| Deact Map 7 | JE 96 | Add XD | Jcn |
| Deact Map 7 | JE 95 | Pull CMP, add XD | existing CMP |
| Deact Map 7 | JE 94 | Bring saw | Large tree across log |
| Deact Map 7 | JE 93 | Pull CMP, add XD | existing CMP |
| Deact Map 7 | JE 92 | Add XD | |
| Deact Map 7 | JE 91 | Add XD | Jcn |
| Deact Map 7 | JE 90 | Add XD | Str comes out here |
| Deact Map 7 | JE 89 | Pull CMP, add XD | existing CMP |
| Deact Map 7 | JE 88 | Add XD | |
| Deact Map 7 | JE 87 | Pull CMP, add XD | existing CMP |
| Deact Map 7 | JE 86 | Pull CMP, add XD | existing CMP |
| Deact Map 7 | JE 85 | Pull CMP, add XD | existing CMP |
| Deact Map 7 | JE 84 | Pull CMP, add XD | Road becomes v brushy here |
| Deact Map 7 | JE 83 | Pull CMP, add XD | existing CMP |
| Deact Map 7 | JE 82 | Add XD | |
| Deact Map 7 | JE 81 | Pull CMP, add XD | existing CMP |
| Deact Map 7 | JE 80 | Add XD | |
| Deact Map 7 | JE 79 | Pull CMP, add XD | existing CMP |

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|-------------------|---------|-------------------------|---|
| Deact Map 7 | JE 78 | Pull CMP, add XD | Str parallels old unnamed grade then flows through cvt here. Leave old spur as is very grown over |
| Deact Map 7 | JE 76 | Add XD | |
| Deact Map 7 | JE 75 | Add XD | |
| Deact Map 7 | JE 74 | Pull WBC | 1*2 appears to be settling on woods side |
| Deact Map 7 | JE 73 | Add WB | SE |
| Deact Map 7 | JE 72 | Add XD | |
| Deact Map 7 | JE 71 | Add XD | |
| Deact Map 7 | JE 70 | Pull CMP, add XD | Existing CMP |
| Deact Map 7 | JE 69 | Add XD | |
| Deact Map 7 | JE 68 | Pull CMP, add XD | Existing CMP |
| Deact Map 7 | JE 65 | No recommendations | Existing WB |
| Deact Map 7 | JE 64 | Add XD | Existing WB |
| Deact Map 7 | JE 63 | No recommendations | Existing WB |
| Deact Map 7 | JE 62 | No recommendations | Existing WB |
| Deact Map 7 | JE 61 | Add XD | |
| H770-OEL-A | | | |
| Deact Map 7 | JE 77 | Remove debris to access | Pile of till |
| H710 | | | |
| Deact Map 7 | JE 66 | No recommendations | Very over grown and flat, no drainage concerns. No deact required |
| Deact Map 7 | JE 67 | Add XD | |
| H760 | | | |
| Deact Map 7 | JE 107 | No recommendations | 20-30 cm diameter dr short road on bench do no recommend deact |
| H107 | | | |
| Deact Map 9 | RN 78 | No recommendations | Wide landing, no road, no deact required |
| H1110 | | | |
| Deact Map 9 | RN 79 | No recommendations | Crossing removed |
| Deact Map 9 | RN 80 | Add XD | |
| H1080 | | | |
| Deact Map 9 | RN 97 | No recommendations | Existing XD |
| Deact Map 9 | RN 96 | No recommendations | Existing XD |
| Deact Map 9 | RN 95 | No recommendations | Existing XD |
| Deact Map 9 | RN 94 | No recommendations | Existing XD |
| Deact Map 9 | RN 93 | No recommendations | Existing XD |
| Deact Map 9 | RN 92 | No recommendations | Existing XD |
| Deact Map 9 | RN 91 | No recommendations | Existing XD |
| Deact Map 9 | RN 90 | No recommendations | Existing XD |
| Deact Map 9 | RN 89 | No recommendations | Deep XD, woodbox pulled |

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|----------------|---------|--------------------|---|
| Deact Map 9 | RN 87 | Pull CMP, add XD | Backup WB |
| Deact Map 9 | RN 86 | Pull CMP, add XD | Backup WB |
| Deact Map 9 | RN 85 | Add XD | Existing RWB, add XD drain to out slope |
| Deact Map 9 | RN 84 | Pull WBC | 3m high, 4mx4m |
| Deact Map 9 | RN 88 | Enhance XD | |
| Deact Map 9 | RN 83 | Add XD | |
| Deact Map 9 | RN 82 | Pull CMP, add XD | Existing CMP |
| Deact Map 9 | RN 81 | Pull CMP, add XD | Existing CMP |
| H1083 | | | |
| Deact Map 9 | RN 99 | No recommendations | crossing pulled around main stream, road deactivated |
| Deact Map 9 | RN 98 | No recommendations | Existing XD |
| H1081 | | | |
| Deact Map 9 | RN 111 | No recommendations | Large log pile, road deactivated past here. Existing XD |
| Deact Map 9 | RN 110 | No recommendations | Existing XD |
| Deact Map 9 | RN 109 | No recommendations | Large log pile, existing XD |
| Deact Map 9 | RN 108 | Add XD | |
| Deact Map 9 | RN 107 | Add XD | End Deact |
| Deact Map 9 | RN 105 | Add XD | |
| Deact Map 9 | RN 104 | Add XD | |
| Deact Map 9 | RN 103 | Pull CMP, add XD | Existing CMP |
| Deact Map 9 | RN 102 | No recommendations | Existing XD |
| Deact Map 9 | RN 101 | Add XD | |
| Deact Map 9 | RN 100 | Enhance XD | |
| H105 | | | |
| Deact Map 9 | RN 115 | No recommendations | Stream crossing removed, road is deactivated |
| Deact Map 9 | RN 114 | No recommendations | Existing XD |
| Deact Map 9 | RN 113 | No recommendations | Existing XD |
| Deact Map 9 | RN 112 | Add XD | |
| H103 | | | |
| Deact Map 8 | RN 4 | No recommendations | Road deactivated with XD |
| Deact Map 8, 9 | RN 6 | No recommendations | Road resloped, need to re-open |
| H1500 | | | |
| Deact Map 7 | JE 118 | No recommendations | No sign of new road all structures pulled on old road |
| H1640 | | | |
| Deact Map 8 | TW 45 | Add XD | |
| Deact Map 8 | TW 46 | Add XD | Wet site |
| Deact Map 8 | TW 47 | Add XD | Draw |
| Deact Map 8 | TW 48 | Pull CMP, add XD | Existing 600 cmp |

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|--------------|---------|------------------------------------|---|
| H1645 | | | |
| Deact Map 8 | TW 44 | Pull CMP, add XD | Existing 600 CMP |
| H1650 | | | |
| Deact Map 8 | TW 50 | Pull CMP, add XD | Existing CMP |
| Deact Map 8 | TW 49 | Pull CMP, add XD | Existing CMP |
| H1660 | | | |
| Deact Map 8 | TW 43 | No work deemed necessary | |
| H1670 | | | |
| Deact Map 8 | TW 37 | No worked needed except XD @ start | No drainage structures or concerns |
| Deact Map 8 | TW 38 | Add XD | Ditch from spur & branch join w no CMP |
| H1680 | | | |
| Deact Map 8 | TW 33 | Pull CMP, add XD | Existing 800 CMP |
| Deact Map 8 | TW 34 | Pull CMP, add XD | Existing 800 CMP |
| H1600 | | | |
| Deact Map 8 | TW 35 | Pull CMP, add XD | Existing 800 CMP |
| Deact Map 8 | TW 36 | Add XD | |
| Deact Map 8 | TW 39 | Pull CMP, add XD | Existing 800 CMP |
| Deact Map 8 | TW 40 | Pull CMP, add XD | Existing 600 CMP |
| Deact Map 8 | TW 41 | Add XD | Ncd draw |
| Deact Map 8 | TW 42 | Pull CMP, add XD | Existing 600 CMP |
| Deact Map 8 | TW 51 | Add XD | Ensure connects to H1540 ditch which joins branch here |
| Deact Map 8 | TW 52 | Pull CMP, add XD | Existing 800 CMP |
| Deact Map 8 | TW 53 | Add XD | Ncd draw |
| Deact Map 8 | TW 54 | Pull WBC | Existing 4 m WBC |
| Deact Map 8 | TW 55 | Pull CMP, add XD | Existing 800 CMP |
| Deact Map 8 | TW 56 | Add XD | Draw |
| Deact Map 8 | TW 57 | Pull CMP, add XD | Existing 600 CMP |
| Deact Map 8 | TW 58 | Add XD | Draw |
| Deact Map 8 | TW 59 | Pull CMP, add XD | Existing 600 CMP |
| Deact Map 8 | TW 60 | Add XD | Existing CMP |
| Deact Map 8 | TW 82 | Add XD | |
| Deact Map 8 | TW 86 | Add XD | |
| Deact Map 8 | TW 87 | Add XD | Real thick cover, likely missed CMP first few hundred of rd |
| H1620 | | | |
| Deact Map 8 | TW 85 | Pull CMP, add XD | Existing 800 CMP |
| Deact Map 8 | TW 84 | No recommendations | OG Cw |
| Deact Map 8 | TW 83 | No recommendations | OG Cw blocking rd |

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|------------------|---------|--------------------------|---|
| H1610 | | | |
| Deact Map 8 | RN 117 | Add XD | |
| Deact Map 8 | RN 116 | Add XD | |
| H800 | | | |
| Deact Map 8 | TW 25 | No work deemed necessary | S6 w drainage pulled, rd heavily overgrown, not worth reopening |
| 500 | | | |
| Deact Map 11 | TW 90 | Pull bridge | 10 m wood bridge, no notable issues |
| Deact Map 11 | TW 91 | Add XD | Steep grade into fish draw |
| Deact Map 11 | TW 92 | Add WB | Southeast |
| Deact Map 11 | TW 93 | Add XD | Topo low |
| Deact Map 11 | TW 94 | Add WB | Northwest, Steep grade down to draw |
| Deact Map 11 | TW 95 | Pull bridge | 10 m wood bridge, no notable issues |
| Deact Map 11 | TW 96 | Add WB | south |
| Deact Map 11 | TW 97 | Pull bridge | 9 m wood bridge |
| Deact Map 11 | TW 98 | Add WB | North |
| Deact Map 11 | TW 99 | Add WB | West |
| Deact Map 10, 11 | TW 100 | Pull bridge | 9 m wood bridge |
| Deact Map 10, 11 | TW 101 | Pull bridge | 8m wood bridge |
| Deact Map 10, 11 | TW 102 | Add WB | Southwest |
| Deact Map 10, 11 | TW 103 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 104 | Pull bridge | 9 m wood bridge , minor subsistence on wood side |
| Deact Map 10, 11 | TW 105 | Pull bridge | 8m portable steel bridge |
| Deact Map 10, 11 | TW 106 | Add XD | Ncd draw |
| Deact Map 10, 11 | TW 107 | Pull CMP, add XD | 600 cmp ncd |
| Deact Map 10, 11 | TW 108 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 109 | Add XD | Draw |
| Deact Map 10, 11 | TW 110 | Pull bridge | 9 m wood bridge |
| Deact Map 10, 11 | TW 111 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 112 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 113 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 114 | Pull bridge | 9 m wood bridge |
| Deact Map 10, 11 | TW 115 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 125 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 130 | Add XD | |
| Deact Map 10, 11 | TW 131 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 132 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 133 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 134 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 135 | Add XD | Wet site |
| Deact Map 10, 11 | TW 136 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 138 | Add XD | Water from spur goes to ditch on 500 |

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|------------------|---------|--------------------|---|
| Deact Map 10, 11 | TW 139 | Add XD | |
| Deact Map 10, 11 | TW 140 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 141 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 142 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 143 | Add XD | |
| Deact Map 10, 11 | TW 144 | Add XD | Small draw |
| Deact Map 10, 11 | TW 145 | Add WB | Northwest. Steep grade back to XD |
| Deact Map 10, 11 | TW 146 | Pull WBC | Existing 5 m WBC |
| Deact Map 10, 11 | TW 147 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 148 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 152 | Pull CMP, add XD | Existing cmp |
| Deact Map 10, 11 | TW 153 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 154 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 155 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 156 | Add XD | |
| Deact Map 10, 11 | TW 167 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 168 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10 | TW 179 | Add XD | |
| Deact Map 10 | TW 180 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10 | TW 181 | Add XD | |
| Deact Map 10 | TW 182 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10 | TW 183 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10 | TW 184 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10 | TW 185 | Pull bridge | 10m wood bridge |
| Deact Map 10 | TW 186 | Add XD | |
| Deact Map 10 | TW 187 | Add XD | |
| Deact Map 10 | TW 188 | Add XD | |
| Deact Map 10 | TW 189 | Pull bridge | 7 m wood bridge |
| H5700 | | | |
| Deact Map 10 | TW 124 | Add WB | Northwest. Steep grade runoff |
| Deact Map 10 | TW 123 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10 | TW 122 | No recommendations | 0.5 m dbh Cw blocking access |
| Deact Map 10 | TW 121 | Add WB | Southwest |
| Deact Map 10 | TW 120 | Add XD | |
| Deact Map 10 | TW 119 | Pull CMP, add XD | Existing plastic 600 cmp |
| Deact Map 10 | TW 118 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10 | TW 117 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10 | TW 116 | Pull CMP, add XD | Existing 600 cmp |
| H5600 | | | |
| Deact Map 10 | TW 126 | Pull bridge | 8 m wood bridge, assessed by heli, no work required beyond here |
| Deact Map 10 | TW 127 | Pull CMP, add XD | Existing 600 cmp |

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|------------------|---------|------------------------------------|--|
| Deact Map 10 | TW 128 | Add XD | Poor visibility, likely CMP in here somewhere |
| Deact Map 10 | TW 129 | Pull CMP, add XD | Existing 600 cmp |
| 550 | | | |
| Deact Map 10 | TW 137 | Pull CMP, add XD | Existing 600 CMP |
| 530 | | | |
| Deact Map 10 | TW 149 | Pull CMP, add XD | Existing 600 CMP |
| Deact Map 10 | TW 150 | Add XD | |
| Deact Map 10 | TW 151 | Add XD | |
| 524 | | | |
| Deact Map 10, 11 | TW 158 | No recommendations | If existed is now a large quarry |
| 520 | | | |
| Deact Map 10, 11 | TW 157 | No recommendations | Big landing no work needed |
| Deact Map 10, 11 | TW 159 | Add XD | |
| Deact Map 10, 11 | TW 160 | Pull CMP, add XD | Existing 800 cmp |
| Deact Map 10, 11 | TW 162 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 163 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 164 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 10, 11 | TW 165 | Add WB | Northeast. Steep grade |
| Deact Map 10, 11 | TW 166 | Add XD | |
| 522 | | | |
| Deact Map 10 | TW 161 | No recommendations | Existing XD here and 15 m back, no work needed |
| 514 | | | |
| Deact Map 10, 11 | TW 170 | No recommendations | |
| 512 | | | |
| Deact Map 10, 11 | TW 173 | Pull CMP, add XD | Existing 600 CMP |
| 510 | | | |
| Deact Map 10, 11 | TW 169 | No recommendations | End of rd Flat grade, only 1m fill & no water issues |
| Deact Map 10, 11 | TW 171 | Pull CMP, add XD, no work required | Existing 600 CMP |
| Deact Map 10, 11 | TW 172 | Pull CMP, add XD | Existing 600 CMP |
| Deact Map 10 | TW 174 | Add XD | |
| Deact Map 10 | TW 175 | Add XD | |
| Deact Map 10 | TW 176 | Add XD | |
| Deact Map 10 | TW 177 | Add XD | |
| Deact Map 10 | TW 178 | Pull CMP, add XD | Existing 600 CMP |
| BR5900 | | | |
| Deact Map 12 | LW 5 | No recommendations | Road is overgrown with deciduous and some coniferous; follows benched terrain; nothing to do back here; 1 WBC observed on way here |
| Deact Map 12 | LW 6 | Pull WBC | 1x3 m |
| Deact Map 12 | LW 7 | No recommendations | Existing XD |
| Deact Map 12 | LW 8 | Add XD | at junction; overgrown with forest but good access otherwise |

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|---------------|---------|--------------------|---|
| BR6300 | | | |
| Deact Map 12 | LG 5 | No recommendations | Existing XD |
| Deact Map 12 | LG 6 | Add XD | |
| Deact Map 12 | LG 7 | Add XD | |
| Deact Map 12 | LG 8 | Add XD | |
| Deact Map 12 | LG 9 | Add XD | |
| Deact Map 12 | LG 10 | Add XD | |
| Deact Map 12 | LG 11 | Pull CMP, add XD | Existing CMP |
| Deact Map 12 | LG 12 | No recommendations | Existing XD |
| Deact Map 12 | LG 13 | Add XD | |
| Deact Map 12 | LG 14 | Add XD | |
| Deact Map 12 | LG 15 | Enhance XD | Existing low XD |
| Deact Map 12 | LG 16 | Add XD | |
| Deact Map 12 | LG 17 | Pull CMP, add XD | Existing CMP |
| Deact Map 12 | LG 18 | Add XD | |
| Deact Map 12 | LG 4 | No recommendations | Borrow pit into bench above steep sw leaving narrow ridge. No water accumulation, ok to leave. |
| Deact Map 12 | LG 19 | Add XD | |
| BR6301 | | | |
| Deact Map 12 | LG 36 | Enhance XD | Existing low XD |
| Deact Map 12 | LG 35 | Add XD | |
| Deact Map 12 | LG 34 | Add XD | |
| Deact Map 12 | LG 33 | Add XD | |
| Deact Map 12 | LG 32 | Add XD | |
| Deact Map 12 | LG 31 | Add XD | |
| Deact Map 12 | LG 30 | Enhance WB | Existing WB southwest |
| Deact Map 12 | LG 29 | Pull CMP, add XD | Existing CMP |
| Deact Map 12 | LG 28 | Add XD | |
| Deact Map 12 | LG 27 | Add XD | |
| Deact Map 12 | LG 26 | No recommendations | Cross ditch drains into burrow pit |
| Deact Map 12 | LG 25 | Add reverse WB | South |
| Deact Map 12 | LG 24 | Pull CMP, add XD | Existing CMP |
| Deact Map 12 | LG 23 | Pull CMP, add XD | Existing CMP |
| Deact Map 12 | LG 22 | Pull CMP, add XD | Existing CMP |
| Deact Map 12 | LG 21 | Pull CMP, add XD | Existing CMP |
| Deact Map 12 | LG 20 | Pull CMP, add XD | Existing CMP |
| Deact Map 12 | LG 3 | Pull CMP, add XD | Existing CMP |
| Deact Map 12 | LG 2 | Pull CMP, add XD | Existing CMP |
| BR6200 | | | |
| Deact Map 12 | LW 49 | No recommendations | Existing XD; forest is very thick with large alder and decid trees for past 50 m and thicker forward; Road is all good and has been deactivated |

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|---------------|---------|--------------------|---|
| Deact Map 12 | LW 48 | No recommendations | Existing XD |
| Deact Map 12 | LW 47 | No recommendations | Existing XD |
| Deact Map 12 | LW 46 | No recommendations | Existing XD |
| Deact Map 12 | LW 45 | No recommendations | Existing XD, road is elevated and flat so far. looks good |
| Deact Map 12 | LW 43 | No recommendations | Existing XD; signs of flow through |
| Deact Map 12 | LW 42 | No recommendations | Existing XD |
| Deact Map 12 | LW 41 | No recommendations | Existing XD |
| Deact Map 12 | LW 37 | No recommendations | Existing XD across junction |
| Deact Map 12 | LW 36 | No recommendations | Big existing XD; Old pipe pulled; Will need to walk machine through; Shift to larger alder and looks like older roads ahead |
| Deact Map 12 | LW 35 | Add XD | start of deact, no work required beyond here |
| Deact Map 12 | LW 34 | Add XD | |
| Deact Map 12 | LW 33 | Add XD | existing reverse waterbar |
| Deact Map 12 | LW 32 | No recommendations | Road roughing/loosening ends |
| Deact Map 12 | LW 31 | Pull CMP, add XD | Existing CMP |
| BR6240 | | | |
| Deact Map 12 | LW 44 | No recommendations | Road is good- overgrown with coniferous forest |
| BR6220 | | | |
| Deact Map 12 | LW 40 | No recommendations | Road is deactivated- all good |
| Deact Map 12 | LW 39 | No recommendations | Existing XD |
| Deact Map 12 | LW 38 | No recommendations | Existing XD |
| BR6010 | | | |
| Deact Map 12 | LW 23 | No recommendations | Established con forest along road; all good up to here with XD at beginning |
| Deact Map 12 | LW 24 | Add XD | At beginning of road |
| BR6000 | | | |
| Deact Map 12 | LW 30 | Pull CMP, add XD | Existing CMP |
| Deact Map 12 | LW 29 | Pull CMP, add XD | Existing CMP |
| Deact Map 12 | LW 27 | Add XD | |
| Deact Map 12 | LW 26 | Pull CMP, add XD | Existing CMP |
| Deact Map 12 | LW 25 | Add XD | |
| Deact Map 12 | LW 22 | Pull CMP, add XD | Existing CMP |
| Deact Map 12 | LW 21 | Add XD | |
| Deact Map 12 | LW 20 | Pull CMP, add XD | Existing CMP |
| Deact Map 12 | LW 19 | No recommendations | no more signs of flow on road prism |
| Deact Map 12 | LW 18 | Add XD | |
| Deact Map 12 | LW 17 | Add XD | flow continues down road; erosion into prism 0.25-0.5 m D; 0.5 m W |
| Deact Map 12 | LW 16 | Add XD | Flow from CMP continues down road |
| Deact Map 12 | LW 15 | Pull CMP, add XD | Existing CMP |

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|------------------------|---------|---|---|
| Deact Map 12 | LW 14 | Add XD, QP to assess section of road for deactivation forward due to high flow rates in ditch | signs of flow in ditch via gravel and slight scouring; cut is upslope of ditch 1-3 m height and cut into a till blanket |
| Deact Map 12 | LW 13 | Pull CMP, add XD | Existing CMP |
| Deact Map 12 | LW 12 | Add XD | road is in good condition overall |
| Deact Map 12 | LW 11 | Pull CMP, add XD | Existing CMP |
| Deact Map 12 | LW 10 | Add XD | Settling in road has created holes 0.25-0.5 m D; WSA for potentially unstable road surface |
| Deact Map 12 | LW 9 | Add XD | Junction is good; road is built up on 30-40% bench |
| North Escalante | | | |
| Deact Map 15, 16 | LG 38 | Pull WBC | Existing WBC |
| Deact Map 15, 16 | LG 39 | Pull WBC | Existing WBC |
| Deact Map 15, 16 | LG 40 | Pull WBC | Existing WBC |
| Deact Map 15, 16 | LG 41 | Add WB | Southwest |
| Deact Map 15, 16 | LG 42 | Pull WBC | Existing WBC |
| Deact Map 15, 16 | LG 43 | Pull CMP, add XD | Existing CMP |
| Deact Map 15, 16 | LG 44 | Pull CMP, add XD | Existing CMP |
| Deact Map 15, 16 | LG 45 | Pull WBC | Existing WBC |
| Deact Map 15, 16 | LG 46 | Pull WBC | Existing WBC |
| Deact Map 15, 16 | LG 47 | Pull CMP, add XD | Existing CMP |
| Deact Map 15, 16 | LG 48 | Pull CMP, add XD | Existing CMP |
| Deact Map 15, 16 | LG 49 | Add WB | West |
| Deact Map 15, 16 | LG 50 | Add WB | West |
| Deact Map 15, 16 | LG 51 | Pull CMP, add XD | Existing CMP |
| Deact Map 15, 16 | LG 52 | Add XD | |
| Deact Map 15, 16 | LG 53 | Pull CMP, add XD | Existing CMP |
| Deact Map 15, 16 | LG 54 | Pull CMP, add XD | Existing CMP |
| Deact Map 15, 16 | LG 55 | Add XD | |
| Deact Map 15, 16 | LG 56 | Pull bridge | metal, 12m. good condition |
| Deact Map 15, 16 | LG 57 | Pull CMP, add XD | Existing CMP |
| Deact Map 15, 16 | LG 58 | Pull bridge | wooden, 8m. |
| Deact Map 15, 16 | LG 59 | Pull CMP, add XD | Existing CMP |
| Deact Map 15, 16 | LG 60 | Pull CMP, add XD | Existing CMP |
| Deact Map 15, 16 | LG 61 | Pull CMP, add XD | Existing CMP |
| Deact Map 15, 16 | LG 62 | Pull CMP, add XD | Existing CMP |
| Deact Map 15, 16 | LG 63 | Pull CMP, add XD | Existing CMP |
| Deact Map 15, 16 | LG 64 | Add XD | |
| Deact Map 15, 16 | LG 65 | Pull CMP, add XD | Existing CMP |
| Deact Map 15, 16 | LG 66 | Pull CMP, add XD | Existing CMP |
| Deact Map 15, 16 | LG 67 | Start MPB | Above fish bearing lake. -90% slope. Minor amount of settling on shoulder |

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|------------------|---------|--------------------|--|
| Deact Map 15, 16 | LG 68 | End MPB | |
| Deact Map 15, 16 | LG 69 | Add XD | |
| Deact Map 15, 16 | LG 70 | Add XD | |
| Deact Map 15, 16 | LG 71 | Add XD | |
| Deact Map 15, 16 | LG 72 | Start LPB | Above fish bearing lake. -90% slope. Failures present in |
| Deact Map 15, 16 | LG 73 | End LPB | |
| Deact Map 15, 16 | LG 74 | Add XD | |
| Deact Map 15, 16 | LG 75 | Pull CMP, add XD | Existing CMP |
| Deact Map 15, 16 | LG 76 | Pull WBC | Existing WBC |
| Deact Map 15, 16 | LG 77 | Add XD | |
| Deact Map 15, 16 | LG 78 | Pull CMP, add XD | Existing CMP |
| Deact Map 15, 16 | LG 79 | Enhance WB | Existing low WB |
| Deact Map 15, 16 | LG 80 | Pull WBC | Existing WBC |
| Deact Map 15 | LG 81 | Add XD | |
| Deact Map 15 | LG 82 | Add XD | |
| Deact Map 15 | LG 83 | Pull CMP, add XD | Existing CMP |
| Deact Map 15 | LG 84 | Pull WBC | Existing WBC |
| Deact Map 15 | LG 85 | Add WB | West |
| Deact Map 15 | LG 86 | Add WB | West |
| Deact Map 15 | LG 87 | Pull WBC | Existing WBC |
| Deact Map 15 | LG 88 | Pull bridge | wooden, 6m. |
| Deact Map 15 | LG 89 | Pull CMP, add XD | Existing CMP |
| Deact Map 15 | LG 90 | Pull CMP, add XD | Existing CMP |
| Deact Map 15 | LG 91 | Pull CMP, add XD | Existing CMP |
| Deact Map 15 | LG 92 | Pull CMP, add XD | Existing CMP |
| Deact Map 15 | LG 93 | Pull bridge | wooden, 15m. |
| Deact Map 15 | LG 94 | Enhance WB | Existing low northeast WB |
| Deact Map 15 | LG 95 | Add XD | |
| Deact Map 15 | LG 96 | Add XD | |
| Deact Map 15 | LG 97 | Pull WBC | Existing WBC |
| Deact Map 14, 15 | LG 98 | Pull CMP, add XD | Existing CMP |
| Deact Map 14, 15 | LG 99 | No recommendations | small slide down slope. 10m wide by 25m long. -55% |
| Deact Map 14, 15 | LG 100 | Enhance XD | Existing low XD |
| Deact Map 14, 15 | LG 101 | Pull CMP, add XD | Existing CMP |
| Deact Map 14, 15 | LG 102 | Pull CMP, add XD | Existing dual pipe |
| Deact Map 14, 15 | LG 103 | Start MPB | Tension cracks 0.5m back from shoulder |
| Deact Map 14, 15 | LG 104 | End MPB | |
| Deact Map 14, 15 | LG 105 | Pull CMP, add XD | Existing CMP |
| Deact Map 14, 15 | LG 106 | Pull CMP, add XD | Existing CMP |
| Deact Map 14, 15 | LG 107 | Add XD | |
| Deact Map 14, 15 | LG 108 | Enhance WB | Existing low WB |
| Deact Map 14, 15 | LG 109 | Pull CMP, add XD | Existing CMP |

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|------------------|---------|--------------------|--|
| Deact Map 14, 15 | LG 110 | Add XD | |
| Deact Map 14, 15 | LG 111 | Add XD | |
| Deact Map 14, 15 | LG 112 | Start HPB | settling fill |
| Deact Map 14, 15 | LG 113 | End HPB | |
| Deact Map 14, 15 | LG 114 | Add XD | |
| Deact Map 14, 15 | LG 115 | Add XD | |
| Deact Map 14, 15 | LG 116 | Start MPB | settling fill |
| Deact Map 14, 15 | TW 271 | No recommendations | 25 m w fill failure joins last & river |
| Deact Map 14 | TW 270 | No recommendations | 30 m w fill failure ran out to river |
| Deact Map 14 | TW 269 | End MPB | Windrow & fill 7 m long w cracks on steep, 2 fill failures, see JK for start |
| Deact Map 14 | TW 268 | Start LPB | Short section spoil piled against timber on steep |
| Deact Map 14 | TW 267 | End LPB | |
| Deact Map 14 | TW 266 | Add XD | |
| Deact Map 14 | TW 265 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 14 | TW 264 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 14 | TW 263 | Pull WBC | 4m WBC |
| Deact Map 14 | TW 262 | Add XD | |
| Deact Map 14 | TW 261 | Pull WBC | 5 m WBC |
| Deact Map 14 | TW 260 | Add XD | |
| Deact Map 14 | TW 258 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 14 | TW 257 | Start LPB | 3-5 m keyed in fill on 80-90% |
| Deact Map 14 | TW 256 | Add XD | continue LPB |
| Deact Map 14 | TW 255 | End LPB | Edge of thru cut back to steep |
| Deact Map 14 | TW 254 | Add XD | |
| Deact Map 14 | TW 253 | Start LPB | Rd on 80-120% w sliver fill above river |
| Deact Map 14 | TW 252 | Add XD | continue LPB, Ncd off bluff |
| Deact Map 14 | TW 251 | Add XD | continue LPB, Ncd off bluff |
| Deact Map 14 | TW 250 | End MPB | |
| Deact Map 14 | TW 249 | Pull bridge | 25 m steel bridge |
| Deact Map 14 | TW 248 | Add WB | North. No ditch, draw below |
| Deact Map 14 | TW 247 | Add XD | Draw |
| Deact Map 14 | TW 246 | Add XD | |
| Deact Map 14 | TW 245 | Start LPB | |
| Deact Map 14 | TW 244 | No recommendations | Rd now 3/4 approx, 3 m long fills w cracks starting @ shoulder |
| Deact Map 14 | TW 243 | End LPB | Steep, rd essentially fb but w sliver fill, s cracks on steep into river |
| Deact Map 14 | TW 242 | Add XD | |
| Deact Map 14 | TW 241 | Add XD | |
| Deact Map 14 | TW 240 | Pull bridge | 10 m wood bridge |
| Deact Map 14 | TW 239 | Add XD | Alder slide maybe, no visible str or structure |

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|------------------|---------|---|--|
| Deact Map 14 | TW 238 | Pull CMP, add XD | Existing 800 cmp |
| Deact Map 14 | TW 237 | Add XD | Rd runoff onto fill @ Ncd |
| Deact Map 14 | TW 236 | Pull WBC | 5 m WBC |
| Deact Map 14 | TW 235 | Pull bridge, confirm has been inspected | 7m wood bridge w subsistence 2m from low edge |
| Deact Map 14 | TW 234 | Pull CMP, add XD | Existing 400 Cmp |
| Deact Map 14 | TW 233 | Add XD | |
| Deact Map 14 | TW 232 | Add XD | |
| Deact Map 14 | TW 231 | Start LPB | 2m fill on near vertical, old fill failure alder |
| Deact Map 14 | TW 230 | End LPB | Steep transitions ridge nose |
| Deact Map 13, 14 | TW 228 | Add XD | |
| Deact Map 13, 14 | TW 227 | Start LPB | Sliver fill to 1-3m long, discontinuous t cracks on steep into |
| Deact Map 13, 14 | TW 229 | No recommendations | Tension cracks present shoulder / 1-3 m long fills now |
| Deact Map 13, 14 | TW 226 | End LPB | End of outer 2 m rd surface settling on steep above river, 1- |
| Deact Map 13, 14 | TW 225 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 13, 14 | TW 224 | Pull CMP, add XD | Existing 600 cmp, jnc to here through cut |
| Deact Map 13, 14 | TW 223 | Add XD | |
| Deact Map 13 | TW 221 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 13 | TW 220 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 13 | TW 219 | Add XD | |
| Deact Map 13 | TW 218 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 13 | TW 217 | Pull CMP, add XD | 400 plastic cmp |
| Deact Map 13 | TW 216 | Pull WBC | 4m WBC |
| Deact Map 13 | TW 215 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 13 | TW 214 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 13 | TW 213 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 13 | TW 212 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 13 | TW 211 | Pull CMP, add XD | Existing 800 cmp |
| Deact Map 13 | TW 210 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 13 | TW 209 | Add XD | Draw |
| Deact Map 13 | TW 208 | Add XD | Draw |
| Deact Map 13 | TW 207 | Pull bridge | Existing 10 m wood bridge |
| Deact Map 13 | TW 206 | Pull CMP, add XD | Existing 1000 cmp |
| Deact Map 13 | TW 205 | Add XD | |
| Deact Map 13 | TW 204 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 13 | TW 203 | Pull CMP, add XD | 600 cmp ncd |
| Deact Map 13 | TW 202 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 13 | TW 201 | Pull CMP, add XD | Existing 600 cmp |
| Deact Map 13 | AS 3 | Add XD | |
| Deact Map 13 | AS 2 | Add XD | |
| Deact Map 13 | TW 196 | Add XD | |

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|--------------|---------|--------------------|--|
| Deact Map 13 | TW 197 | Add XD | |
| Deact Map 13 | TW 195 | Add WB | Southeast |
| Deact Map 15 | TW 194 | Add XD | End of deact |
| E510 | | | |
| Deact Map 16 | LW 97 | No recommendations | bridge has been pulled forward; all good forward; no point on coming to deactivated section of road |
| Deact Map 16 | LW 96 | No recommendations | Existing XD |
| Deact Map 16 | LW 95 | No recommendations | Existing XD; end of resloped road |
| Deact Map 16 | LW 94 | No recommendations | recountouring continues |
| Deact Map 16 | LW 93 | No recommendations | Road has been resloped forward and woody debris placed upon moving forward |
| Deact Map 16 | LW 92 | No recommendations | Existing XD |
| Deact Map 16 | LW 91 | No recommendations | Existing reverse waterbar |
| Deact Map 16 | LW 90 | No recommendations | Existing large XD |
| Deact Map 16 | LW 89 | No recommendations | Existing XD |
| Deact Map 16 | LW 88 | No recommendations | Existing XD |
| Deact Map 16 | LW 87 | No recommendations | Junction to other spur is here and is very overgrown with coniferous and decid trees- all good |
| Deact Map 16 | LW 86 | Add XD | |
| Deact Map 16 | LW 85 | Pull CMP, add XD | Existing CMP |
| Deact Map 16 | LW 84 | Start HPB | WSA for rockfall through HPB section; pulled back material can be used to buttress ravelling slope |
| Deact Map 16 | LW 83 | Add XD | |
| Deact Map 16 | LW 82 | Pull CMP, add XD | Existing CMP |
| Deact Map 16 | LW 81 | End HPB | Contine WSA- TC extend 3-4 m into road with displacement 0.5 -1 m on outside 2 m of road |
| Deact Map 16 | LW 80 | Add XD | |
| Deact Map 16 | LW 79 | Add XD | |
| Deact Map 16 | LW 78 | No recommendations | Some TC become visible but likely is woody debris settling; downslope is 55-65% for 15 m then becomes gentle |
| Deact Map 16 | LW 77 | Pull CMP, add XD | Existing CMP |
| Deact Map 16 | LW 76 | Add XD | no signs of recent flow here; stream has been diverted somewhere upstream to forward Xing |
| Deact Map 16 | LW 75 | Start LPB | |
| Deact Map 16 | LW 74 | End LPB | WSA for rockfall on approach to xing; Continue WSA- Fill is above stream; TC extend 0.5-2 m into road; slight displacement 0.25-0.5 m; till irreg overlies R on approach and outcrops in areas on approach |
| Deact Map 16 | LW 73 | Add XD | |

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|------------------|---------|--|---|
| Deact Map 16 | LW 72 | Add XD | |
| Deact Map 16 | LW 71 | Add XD | |
| Deact Map 16 | LW 70 | Start LPB | |
| Deact Map 16 | LW 69 | End LPB | Blocky material between pullback isn't easy to retrieve which is why we stopped pullback |
| Deact Map 16 | LW 68 | Add XD | |
| Deact Map 16 | LW 67 | Start LPB | TC extend 2-3 m into road; some settling and displacement; till veneer over bedrock 0.1-1 D with CW overlying |
| Deact Map 16 | LW 66 | Add XD | Continue LPB, pooled water |
| Deact Map 16 | LW 65 | Add XD | continue LPB |
| Deact Map 16 | LW 64 | End LPB | |
| Deact Map 16 | LW 63 | Add XD | |
| Deact Map 16 | LW 61 | Add armoured XD | |
| Deact Map 16 | LW 62 | Start HPB | slopes were -60-80%; Cm in cut. 0-5 m D; mostly rubbly fill; R starts outcropping forward |
| Deact Map 16 | LW 60 | Add armoured XD | WSA- rockfall |
| Deact Map 16 | LW 59 | Add armoured XD | Continue HPB; TC start extending 1-2 m into road forward and then increase to 3 m |
| Deact Map 16 | LW 58 | No recommendations | Continue HPB- continue WSA for rockfall; WSA for holes in road prism 1-2 m D 0.5 m W on outside 2-3 m of road starts. Cut is switching more to rock instead of colluvium; blocky rubble is deposited amongst second gen forest; TC continue extending up to 4 m into prism; 3-4 m W for excavator |
| Deact Map 16 | LW 57 | Add armoured XD | Continue HPB. TC extend 2-3 m into prism; Cm upslope of road in cut could be incorporated into failure; small cones on road overlapping ditch and onto 2 m of inside road prism; HPB will help buttress |
| Deact Map 15, 16 | LW 56 | Start LPB End HPB and Add XD; WSA for rockfall forward | settling on outside edge extends 1 m into road prism with up to 0.5 m is displacement; 3/4 bench over bedrock with rubbly fill and small windrow on outside edge to pull back; TC start forward; C start depositing on road forward |
| Deact Map 15, 16 | LW 55 | Pull CMP, add XD | Existing CMP |
| Deact Map 15, 16 | LW 54 | End LPB | starting E510 assessment from this point and will finish area behind while walking back |
| Deact Map 15, 16 | LW 98 | Add XD | Steep downslope -80-100%; cut is into bedrock and ~5 m tall |
| Deact Map 15, 16 | LW 99 | Add XD | |
| Deact Map 15, 16 | LW 100 | Add XD | |
| Deact Map 15, 16 | LW 101 | Add XD | |

Appendix A: Road Deactivation Recommendations for Stewardson Short-Term Roads

| Road/# | Station | Recommendation | Comments |
|------------------|---------|---|---|
| Deact Map 15, 16 | LW 102 | Enhance XD | small ditch eroded into road from flow |
| Deact Map 15, 16 | LW 103 | Start MPB | TC extend 2-4 m into road; 0.5 m displacement; |
| Deact Map 15, 16 | LW 104 | End MPB | bit of a windrow with settling/TC |
| Deact Map 15, 16 | LW 105 | Add XD | |
| Deact Map 15, 16 | LW 106 | Start LPB | TC extend 0.5-2 m into road; some settling with slight displacement |
| Deact Map 15, 16 | LW 107 | Add XD | |
| Deact Map 15, 16 | LW 108 | End LPB | |
| Deact Map 15, 16 | LW 109 | Add XD | |
| B110 | | | |
| Deact Map 13 | TW 222 | No works required | Mature conifers no rd surface visible |
| BR100 | | | |
| Deact Map 13 | TW 259 | No works required | Bridge pulled |
| Z1900 | | | |
| Deact Map 17 | DM 1 | Installation of All-Steel Portable bridge required for access, pull following deactivation of up-chain bridge | Survey and design completed by OEL |
| Deact Map 17 | DM 2 | Pull bridge | wood bridge |

Appendix B: Road Reactivation Recommendations for HE780 and HE600/610

| Road/Map # | Station | Recommendation | Comments |
|--------------|-----------|---|--|
| HE780 | | | |
| React Map 5 | JE 1 | clean inlet | existing CMP |
| React Map 5 | JE 4 | clean inlet | existing CMP, plastic pipe |
| React Map 5 | JE 5 | clean inlet | existing CMP, plastic pipe |
| React Map 5 | JE 6 | P.Eng inspection required | 7 m all steel portable |
| React Map 5 | JE 7 | clean inlet | existing CMP, plastic pipe |
| React Map 5 | JE 9 | clean inlet | existing CMP |
| React Map 5 | JE 10 | clean inlet | existing CMP, plastic pipe |
| React Map 5 | JE 11 | no recommendation | End React |
| HE600 | | | |
| React Map 6 | JE 39 | no recommendation | Large alder on road edges small on driving surface no pick up access |
| React Map 6 | JE 60 | clean inlet | existing CMP |
| React Map 6 | JE 58 | retain existing XD | existing XD |
| React Map 6 | JE 57 | retain existing XD | existing XD |
| React Map 6 | JE 55 | retain existing XD | existing XD |
| HE610 | | | |
| React Map 6 | JE 53 | clean inlet, start excavate and reconstruct | holes in road |
| React Map 6 | JE51 + 20 | End excavate and reconstruct | |
| React Map 6 | JE 50 | retain existing XD | existing XD |

Appendix C: Road Reactivation Recommendations for Hotsprings Mainline

| Road/Map # | Station | Recommendation | Comments |
|----------------------------|--------------|---|--|
| Hotsprings Mainline | | | |
| React Map 1 | JK 1 | Clean and SC debris | small rock fall in ditch |
| React Map 1 | JK 3 | Start LPB | pile of debris on road corner, possible settling |
| React Map 1 | JK 4 | End LPB | |
| React Map 1 | JK 5 | Start clean & brush ditchline | 6m long wood bridge, bridge inspection completed |
| React Map 1 | JK 8 | No recommendations | steel bridge 20m looks good |
| React Map 1 | JK 11 | clean CMP | partially plugged plastic culvert |
| React Map 1 | JK 64 | No recommendations | till cut, shallow ditch |
| React Map 2 | JK 12 | No recommendations | steel bridge, 20m long, minor rail damage, missing delineators |
| React Map 2 | JK 66 | No recommendations | brushy ditchline |
| React Map 2 | JK 67 | No recommendations | brush & clean ditch |
| React Map 2 | JK 68 | No recommendations | brush & clean ditch |
| React Map 2 | JK 23 | No recommendations | steel bridge, looks good, 17m |
| React Map 2 | JK 24 | No recommendations | good CMP |
| React Map 3 | JK 69 | No recommendations | brushy ditch and fill, brush & clean ditch |
| React Map 3 | JK 70 | No recommendations | brushy ditch and fill, brush & clean ditch |
| React Map 3 | JK 36 | No recommendations | brushy ditch, but all CMPs seem to be clean |
| React Map 3 | JK 41 | End clean & brush ditchline | brushy ditches continue |
| React Map 3 | JK 42 | Add WB | bit of road wash down steep grade, road edge waterbars |
| React Map 3 | JK 43 | Add WB | |
| React Map 4 | JK 44 | Add WB | |
| React Map 4 | JK 45 | Add WB | steep grade continues |
| React Map 4 | JK 46 | Add WB | |
| React Map 4 | JK 48 | Add reverse WB | East. Road slopes a bit other way |
| React Map 4 | JK 47 | Add WB | |
| React Map 4 | JK 49 | Add WB | |
| React Map 4 | JK 50 | Add reverse WB | East |
| React Map 4 | JK 51 | Add reverse WB, start brush & clean ditch | RWB (east), clean ditch (east side), bursh |
| React Map 4 | JK 52 | End brush & clean ditch | brush west side |
| React Map 4 | JK 53 | Start clean ditch | west side |
| React Map 4 | JK 54 | End clean ditch | steep colluvial cuts will continue to ravel |

Appendix D: Road Reactivation Recommendations for Stewardson Mainline

| Road/Map # | Station | Recommendation | Comments |
|----------------------------|---------|--|---|
| Stewardson Mainline | | | |
| React Map 4 | AH 9 | No recommendations | Bridge - 5m wood |
| React Map 4 | AH 10 | P. Eng inspection. Start clean ditch | Bridge - Wood bridge, downstream edge minor subsidence |
| React Map 4 | AH 11 | End clean ditch line | |
| React Map 4 | AH 12 | Replace CMP | Plugged 600 CMP |
| React Map 4 | AH 13 | Clean CMP | Partially obstructed 800 CMP, 15% full of gravels. Still functional. |
| React Map 4 | AH 14 | No recommendations | Bridge - 5 m wood in good condition |
| React Map 4 | AH 16 | Start brushing & clean ditch | Brushing may be required starting here (continues from here to at least 7.5k bridge). |
| React Map 4 | AH 17 | Clean CMP inlet | Existing CMP - Low to nonexistent ditch between here and intersection on N side |
| React Map 4 | AH 18 | Add CMP | Concave wet site |
| React Map 4 | AH 20 | P. Eng inspection of bridge, Start resurfacing | Bridge - 5m wood, 1m of outer lower rd surface sagging |
| React Map 4 | AH 21 | End resurfacing | 1200 CMP functional, prism looks good. This culvert to last bridge may require resurfacing. |
| React Map 4 | AH 22 | Clean CMP inlet | Existing CMP |
| React Map 4 | AH 23 | No recommendations | Existing CMP |
| React Map 4 | AH 24 | Clean CMP inlet | Existing 800 CMP |
| React Map 4 | AH 25 | No recommendations | Existing CMP |
| React Map 4 | AH 26 | No recommendations | Existing CMP |
| React Map 4 | AH 28 | Construct engineered ford | P.Eng Ford Design completed by OEL |
| React Map 4 | AH 31 | Start LPB of fills + 0.5m shoulder, move road in 0.5m | 4.5 m usable road width. 4-5 m vert R cut, +70 above. 2m w ditch line, approx 6m long fill @ 85% on 60-70% slope. Outer 0.5m of shoulder and fs settling. |
| React Map 4 | AH 32 | End LPB of fills + 0.5m shoulder, move road in 0.5m | Plenty of room in oversized ditch to move road in |
| React Map 4 | AH 33 | No recommendations | Existing CMP |
| React Map 4 | AH 34 | No recommendations | Existing CMP |
| React Map 4 | AH 35 | Start MPB, including 1-1.5m outer rd surface, move road in 1m. | 4.5m usable rd with 2m ditch. 5-6m bedrock cut. Outer 2m rd surface settling. +50%. |
| React Map 4 | AH 36 | End MPB, including 1-1.5m outer rd surface, move road in 1m. | |

Appendix D: Road Reactivation Recommendations for Stewardson Mainline

| Road/Map # | Station | Recommendation | Comments |
|----------------|---------|--|--|
| React Map 4, 5 | AH 37 | Start excavate outer edge, remove fines and woody material. Rebuild outer edge. | 4-4.5m usable rd width. 4-5m vert R cut, +40-50% above. 6m fill on 15m l 75% slope to bench. Outer 1-1.5m resurface settling. |
| React Map 4, 5 | AH 38 | End excavate outer edge, remove fines and woody material. Rebuild outer edge. | |
| React Map 4, 5 | AH 39 | No recommendations | Existing CMP |
| React Map 5 | AH 40 | No recommendations | Existing WBC |
| React Map 5 | AH 41 | No recommendations | Alder across road approx 0.3m dbh |
| React Map 5 | AH 44 | No recommendations | 2x small Hw across rd |
| React Map 5 | AH 46 | No recommendations | Existing 600 CMP x2, overhanging by 3m |
| React Map 5 | AH 47 | P. Eng inspection required | 12m wooden bridge, ponding on E side |
| React Map 5 | AH 48 | No recommendations | Cw 0.35m dbh + 6-7 smaller trees down across road |
| React Map 5 | AH 49 | Add CMP | S6 to NCD runs into ditch line and ponds here, no culvert. |
| React Map 5 | AH 50 | No recommendations | Existing CMP |
| React Map 5, 6 | AH 51 | No recommendations | Existing CMP |
| React Map 5, 6 | AH 52 | No recommendations | Existing CMP |
| React Map 6 | AH 54 | No recommendations | 2x small conifers across rd |
| React Map 6 | AH 55 | No recommendations | 0.3m dbh Hw high across rd |
| React Map 6 | AH 57 | No recommendations | Existing CMP |
| React Map 6 | AH 58 | Collapsing downstream side prism, daylighting to stream, P. Eng to inspect and possibly replace. | |
| React Map 6 | AH 59 | No recommendations | 0.25 m dbh alder across rd |
| React Map 6 | AH 61 | Start MPB | See AH60 |
| React Map 6 | AH 60 | Relocate 2x CMP. Place woods side +2m. Armour intakes. End MPB across draw. Place guard log on outside edge. | Big fill around existing 2x existing 800 CMP, one is fully plugged other open. Some retrogression on ditch side of road prism. 7m l x 3m h section of -80% fill through stream draw. Depth of fill unknown likely 10m w x 5m h but bottom 2m is blocks and ok. Fill slope minor retrogression. |
| React Map 6 | AH 62 | No recommendations | 0.3m dbh alder across rd |
| React Map 6 | AH 63 | No recommendations | 0.4m dbh alder across rd |

Appendix D: Road Reactivation Recommendations for Stewardson Mainline

| Road/Map # | Station | Recommendation | Comments |
|----------------|---------|--|--|
| React Map 6 | AH 64 | Add CMP | Will likely require ditch cleaning. 8-10m till cut slope above rd is ravelling. Multiple alder across rd. Windthrow off till cutslope. |
| React Map 6 | AH 65 | Add CMP, end brushing & clean ditch | Saturated road continues from last, wet draw |
| React Map 6 | JE 13 | Start LPB | Tc and settling 1-2 m from road edge |
| React Map 6 | JE 12 | End LPB | Sufficient too. To move road in if reqd |
| React Map 6 | JE 14 | Install new bridge | Draft P.Eng bridge design completed by OEL |
| React Map 6 | JE 15 | Start excavate and reconstruct | Minor setting and 10 cm hole in road. Suspect old fill. Only 50% below |
| React Map 6 | JE 16 | End excavate and reconstruct | |
| React Map 6 | JE 17 | Start LPB | Settling now over steep sufficient road width to move in if reqd. 2 m H by 0.3 V |
| React Map 6 | JE 19 | End LPB | |
| React Map 6 | JE 20 | Bring saw | WT across road. Bring saw can't see any settling |
| React Map 6 | JE 21 | Install CMP if not already installed creek is flowing across road below wt | |
| React Map 6 | JE 22 | Clean inlet excavate and repack around cmp | Existing CMP. holes in road |
| React Map 6 | JE 23 | Clean inlet | Existing CMP |
| React Map 6 | JE 24 | Clean inlet | Existing CMP |
| React Map 6 | JE 25 | Clean inlet | Existing CMP |
| React Map 6 | JE 26 | Start LPB, move road into slope as reqd | 5-6 m of road width will remain after pb cutslope is 5 m of tills |
| React Map 6 | JE 27 | End LPB | |
| React Map 6 | JE 28 | Clean inlet | Existing CMP |
| React Map 6 | JE 29 | Clean inlet | Existing CMP |
| React Map 6 | JE 30 | Clean inlet | Existing CMP |
| React Map 6 | JE 31 | Bring saw | Tree across road |
| React Map 6 | JE 32 | Discuss during react | Settling of rock fill very localized. Could excavate and reconstruct- 80% beyond road edge |
| React Map 6 | JE 33 | Clean inlet | Existing CMP |
| React Map 6 | JE 34 | Clean inlet | Existing CMP |
| React Map 6 | JE 37 | Clean inlet | Existing CMP |
| React Map 6, 7 | JE 201 | Start excavate to bench and kir | |

Appendix D: Road Reactivation Recommendations for Stewardson Mainline

| Road/Map # | Station | Recommendation | Comments |
|----------------|---------|---|---|
| React Map 6, 7 | JE 35 | End excavate and reconstruct | Bit slopey but no tension cracks. Reassess when opening up road very brushy. -80% fill slope 3 m of slopes road edge at 25%. Cutslope is 5 m high. Alternatively MPB and move road in |
| React Map 7 | JE 36 | Clean inlet | Existing CMP |
| React Map 7 | JE 101 | Start excavate and reconstruct | Road is outsloped/setteling with 0.5 m dia hole .5 m from road edge -35% |
| React Map 7 | JE 102 | End excavate and reconstruct | |
| React Map 7 | JE 103 | Clean inlet | Existing CMP |
| React Map 7 | JE 104 | Start excavate and reconstruct | Hole from water or rotted out log or combo |
| React Map 7 | JE 106 | P.Eng. inspection required | WBC |
| React Map 7 | JE 105 | End excavate and reconstruct | Stop at WBC |
| React Map 7 | JE 108 | excavate and reconstruct | 0.5 m hole in road. No drainage structure no stream above no water in ditch gentle below |
| React Map 7 | JE 109 | No recommendations | Pit and potential Heli pad |
| React Map 7 | JE 110 | excavate and reconstruct | Large fill failing 2-3 m at 80%; bench 1-2 m hole at least 0.5 m deep no WBC no water issues |
| React Map 7 | JE 112 | excavate and reconstruct, start clean ditch | 0.5 m deep hole in fill/ middle of road |
| React Map 7 | JE 113 | Excavate and replace pipe | Hole on fill side at cmp. Inlet is crushed |
| React Map 7 | JE 114 | End clean ditch | Existing WBC 1*3 |
| React Map 7, 8 | JE 115 | No recommendations | Existing WBC 1*4 under sized? |
| React Map 7, 8 | JE 200 | Start excavate and reconstruct | 5 m of road inside tension cracks |
| React Map 8 | JE 199 | End excavate and reconstruct | Tension cracks -60%(5m);bench |
| React Map 8 | JE 198 | Clean inlet | Existing CMP |
| React Map 8 | JE 197 | P.Eng. inspection required | bridge collapsing two large holes |
| React Map 8 | JE 196 | Clean inlet | Existing CMP in old WBC |
| React Map 8 | JE 195 | Clean inlet | Existing CMP |
| React Map 8 | JE 194 | Clean inlet | Existing CMP in old WBC |
| React Map 8 | JE 193 | Clean inlet | Existing CMP |
| React Map 8 | JE 192 | Clean inlet | Existing CMP in old WBC |
| React Map 8 | JE 191 | Clean inlet | Existing CMP in old WBC |
| React Map 8 | JE 190 | Clean inlet | Existing CMP |

Appendix D: Road Reactivation Recommendations for Stewardson Mainline

| Road/Map # | Station | Recommendation | Comments |
|------------------|---------|---|---|
| React Map 8 | JE 189 | Clean inlet | Existing CMP |
| React Map 8 | JE 188 | Start excavate and reconstruct | |
| React Map 8 | JE 187 | End excavate and reconstruct | Settling above bench |
| React Map 8 | TW 32 | Replace bridge, P.Eng design required | 9 m collapsing log bridge |
| React Map 8 | TW 31 | Replace wbc | 5 m WBC collapsing lower edge |
| React Map 8 | TW 30 | No recommendations | 1000 CMP functioning |
| React Map 8 | TW 29 | No recommendations | 1000 CMP functioning |
| React Map 8 | TW 28 | No recommendations | 1000 CMP functioning |
| React Map 8, 10 | TW 27 | P.Eng. inspection required | 20m log bridge |
| React Map 10 | TW 26 | No recommendations | 5 m WBC, no obvious instability, assess if hauling |
| React Map 10 | TW 24 | No recommendations | 1000 CMP functioning |
| React Map 10 | TW 23 | P.Eng. inspection required | 6m WBC, no obvious instability |
| React Map 10 | TW 21 | P.Eng. inspection required | 10.5m wood bridge, no obvious instability |
| React Map 10 | TW 20 | No recommendations | 600 CMP functioning |
| React Map 10 | TW 19 | No recommendations | 600 CMP functioning |
| React Map 10 | TW 18 | No recommendations | 600 CMP functioning |
| React Map 10 | TW 17 | Replace 600 cmp | 600 CMP appears to have holes, water enters pipe but comes out not in pipe |
| React Map 10, 11 | TW 16 | Start brushing & cleaning | 600 CMP functioning |
| React Map 10, 11 | TW 13 | Start MPB, including 1-1.5m outer rd surface, move road in 1m. | |
| React Map 10, 11 | TW 14 | End MPB, start HPB+ place guard log, move rd into ditch if required | 10 m long 0.1 m w crack in dead middle of rd |
| React Map 10, 11 | TW 15 | End HPB+, start HPB, move rd 1m into ditch | Rd narrows here, no longer crack in centre, but still unstable fill & cracks in shoulder , 10 m long 0.1 m w crack in dead middle of rd |
| React Map 10, 11 | TW 12 | | continue HPB |
| React Map 10, 11 | TW 11 | End HPB | include outer 4 of rd surface, could rebuild or move rd 1m into ditch |
| React Map 10, 11 | TW 10 | Start HPB | Start unstable outer edge |
| React Map 10, 11 | TW 9 | No recommendations | Shift to 10 m vert R cut w filled ditch, still 3m sagging outer rd surface w similar sized oversteepened fills, |

Appendix D: Road Reactivation Recommendations for Stewardson Mainline

| Road/Map # | Station | Recommendation | Comments |
|------------------|---------|--|---|
| React Map 10, 11 | TW 8 | End HPB, move rd into ditch if required, place guard log on outside edge | No cut work required plenty of room, Outer 3m of rd including surface & 7 m long fill settling w discontinuous cracks |
| React Map 10, 11 | TW 7 | Excavate fill including 0.5m of outer shoulder, remove fines & wdb, repack | |
| React Map 10, 11 | TW 6 | Brushing & resurfacing required | |
| React Map 10, 11 | TW 5 | Replace wbc | 5 m WBC w sagging down str edge |
| React Map 10, 11 | TW 4 | No recommendations | 0.65 DBH Hw on rd, too slow to measure meters in field, get in office |
| React Map 10, 11 | TW 3 | End brushing & cleaning | 5m g ch +-5% mtp, already surveyed, bridge out |
| React Map 10, 11 | TW 2 | Install cmp | 2m g ch flowing subsurface below rd, no visible structure, stays subsurface below rd |
| React Map 11 | RN 8 | Add CMP | Natural drainage, water pooled on road |
| React Map 11 | RN 9 | No recommendations | Existing woodbox culvert functioning |
| React Map 11 | RN 10 | Add CMP | |
| React Map 11 | RN 11 | No recommendations | Existing 600 CMP |
| React Map 11 | RN 12 | Start LPB, end haul | Slumping and tension cracks 1m back |
| React Map 11 | RN 13 | End LPB, end haul | |
| React Map 11 | RN 14 | No recommendations | Existing 600 CMP |
| React Map 11 | RN 15 | No recommendations | Existing woodbox culvert, functioning |
| React Map 11 | RN 16 | No recommendations | Existing 800 CMP, stream flowing |
| React Map 11 | RN 17 | No recommendations | Existing stream crossing |
| React Map 11 | RN 19 | Add CMP | End of active road, road grassed in but still useable |
| React Map 11 | RN 20 | No recommendations | Existing 1000 CMP, functioning |
| React Map 11, 12 | RN 21 | Add CMP | Road degrades, not easily accessible by vehicle |
| React Map 12 | RN 22 | Add CMP | Water flowing along ditchline |
| React Map 12 | RN 23 | Add CMP | Cross drain |
| React Map 12 | RN 24 | Add CMP | |
| React Map 12 | RN 25 | Add CMP | Cross drain |
| React Map 12 | RN 26 | Add CMP | Cross drain |
| React Map 12 | RN 27 | Add CMP | Cross drain |
| React Map 12 | RN 28 | No recommendations | Existing 1000 CPP, functioning well |
| React Map 12 | RN 29 | Add CMP | |
| React Map 12 | RN 30 | Add CMP | Check for existing CMP once cleared |
| React Map 12 | RN 31 | Add CMP | |
| React Map 12 | RN 32 | Add CMP | |
| React Map 12 | RN 33 | Add CMP | Cross drain |

Appendix D: Road Reactivation Recommendations for Stewardson Mainline

| Road/Map # | Station | Recommendation | Comments |
|------------------|---------|---|--|
| React Map 12 | RN 34 | Add CMP | |
| React Map 12 | RN 35 | Add CMP | Edge of slide |
| React Map 12 | RN 36 | Add CMP | Slide debris, large woody debris across road reconstruct and clear debris. Stream crossing at RN36. RN36 photo looking upslope towards head. RN (1) photo looking downslope toward toe |
| React Map 12 | RN 37 | Add CMP | Edge of slide, clean woody debris |
| React Map 12 | RN 38 | No recommendations | Existing CMP , stream crossing |
| React Map 12 | RN 39 | Clean inlet and reinstall CMP | Small slide deposition on road |
| React Map 12 | RN 40 | Add CMP | Water flowing across the road |
| React Map 12 | RN 41 | No recommendations | Road settling, rework/rebuild |
| React Map 12 | RN 42 | No recommendations | Existing 1000 CMP, functioning well, stream crossing |
| React Map 12 | RN 43 | Add CMP | Stream crossing |
| React Map 12 | RN 44 | No recommendations | End of stream divergence, stream heads downslope, end of slide edge |
| React Map 12 | RN 45 | No recommendations | Armour and realign channel to stay in main channel. Stream diverges |
| React Map 12 | RN 47 | Rebuild | Bridge 1, wiped out by debris slide, 5m span. P.Eng bridge design |
| React Map 12 | RN 48 | No recommendations | Slide edge |
| React Map 12 | RN 49 | P.Eng. inspection required | Existing WBC/log bridge. 3 trees stacked for 6m along on either side. Stream down below |
| React Map 12 | RN 50 | No recommendations | Existing CMP |
| React Map 12 | RN 51 | P.Eng. inspection required | Log Bridge over stream |
| React Map 12, 13 | RN 52 | No recommendations | Existing stream crossing |
| React Map 12, 13 | RN 53 | No recommendations | Existing 600 CMP, stream crossing |
| React Map 12, 13 | RN 54 | No recommendations | Existing 800 CMP, stream flowing |
| React Map 13 | RN 55 | No recommendations | Existing CMP |
| React Map 13 | RN 56 | No recommendations | Existing woodbox culvert functioning |
| React Map 13 | RN 57 | No recommendations | Guard logs end coming out of crossing |
| React Map 13 | RN 58 | No recommendations | P.Eng bridge design, buried log bridge due to slide debris |
| React Map 13 | RN 59 | No recommendations | Road blocked, end of passable road due to slide |
| React Map 13 | RN 60 | No recommendations | Existing 600 CMP |
| React Map 13 | RN 61 | No recommendations | Existing 1000 CMP, functioning well, stream crossing |
| React Map 13 | RN 62 | Add CMP | Stream crossing |
| React Map 13 | RN 63 | Excavate and reconstruct to repair hole in road | Existing 800 CMP, stream flowing, hole in road near crossing |
| React Map 13 | RN 64 | No recommendations | Existing 600 CMP |

Appendix D: Road Reactivation Recommendations for Stewardson Mainline

| Road/Map # | Station | Recommendation | Comments |
|------------------|---------|---|---|
| React Map 13 | RN 65 | No recommendations | Small hole in road, rework road surface |
| React Map 13 | RN 66 | No recommendations | Existing 800 CPP, stream flowing |
| React Map 13 | RN 67 | No recommendations | Existing 600 CMP |
| React Map 13 | RN 68 | No recommendations | Existing 1000 CPP, functioning |
| React Map 13 | RN 69 | No recommendations | Existing 600 CMP |
| React Map 13 | RN 70 | No recommendations | Existing woodbox culvert functioning |
| React Map 13 | RN 71 | No recommendations | Existing 1000 CPP, functioning well |
| React Map 13 | RN 72 | Clean ditchline | Old slide debris |
| React Map 13 | RN 73 | No recommendations | Existing 600 CMP |
| React Map 13, 14 | RN 74 | No recommendations | Existing woodbox culvert functioning over stream, 4m long |
| React Map 13, 14 | RN 75 | No recommendations | Existing 600 CMP |
| React Map 13, 14 | RN 76 | Clean inlet | Existing woodbox culvert functioning |
| React Map 13, 14 | RN 119 | No recommendations | Existing 600 CMP |
| React Map 13, 14 | RN 120 | Clean inlet | Existing 600 CMP |
| React Map 13, 14 | RN 121 | Replace CMP and clean inlet | Damaged CMP |
| React Map 13, 14 | RN 122 | No recommendations | Existing 600 CMP |
| React Map 13, 14 | RN 123 | No recommendations | Existing 600 CMP |
| React Map 13, 14 | RN 124 | P.Eng. inspection required | Functioning 5m WBC over 7m wide road with collapsed hole, S5 stream crossing |
| React Map 13, 14 | RN 125 | No recommendations | Existing 600 CMP |
| React Map 14 | RN 126 | No recommendations | Existing 600 CMP, Intake damaged, still functioning , stream crossing |
| React Map 14 | RN 127 | No recommendations | Existing 600 CMP |
| React Map 14 | RN 128 | No recommendations | Existing 600 CMP |
| React Map 14 | RN 129 | No recommendations | Existing 1000 CMP, functioning |
| React Map 14 | RN 130 | No recommendations | Existing 800 CMP |
| React Map 14 | RN 131 | No recommendations | Existing 1000 CMP |
| React Map 14 | RN 132 | No recommendations | Existing 600 CMP, damaged intake |
| React Map 14 | RN 133 | Start clean ditchline, P.Eng. inspection required | Log bridge/WBC 5-6m long, soft sediments on the downstream shoulder settling, |
| React Map 14 | RN 134 | No recommendations | Existing 800 CMP |
| React Map 14 | RN 135 | End clean ditchline | Existing CMP |
| React Map 14 | RN 136 | No recommendations | Existing 600 CMP |
| React Map 14 | RN 137 | No recommendations, P.Eng. inspection required | Log bridge, 8-10m long, stream crossing |
| React Map 14 | RN 138 | No recommendations | Existing 800 CMP |
| React Map 14 | RN 139 | No recommendations | Existing 800 CMP, functioning, NCD stream crossing |
| React Map 14 | RN 140 | No recommendations | Existing 600 CMP, functioning |

Appendix D: Road Reactivation Recommendations for Stewardson Mainline

| Road/Map # | Station | Recommendation | Comments |
|------------------|---------|---|--|
| React Map 14 | RN 141 | No recommendations | Existing 1000 CPP, functioning |
| React Map 14 | RN 142 | Start clean ditchline | Existing 600 CMP, functioning |
| React Map 14 | RN 143 | End clean ditchline | |
| React Map 14 | RN 144 | No recommendations | Existing CMP, functioning |
| React Map 14 | RN 145 | No recommendations | Existing CMP, functioning |
| React Map 14 | RN 146 | No recommendations | Existing 1000 CMP, functioning well, stream crossing |
| React Map 14 | RN 147 | No recommendations | Existing 600 CMP , stream crossing |
| React Map 14, 15 | RN 148 | No recommendations | Existing 1000 CMP, functioning well, stream crossing |
| React Map 14, 15 | RN 149 | No recommendations | Existing 600 CMP, NCD crossing, down trees across road |
| React Map 14, 15 | RN 150 | No recommendations | Existing 600 CMP, functioning |
| React Map 15 | RN 151 | No recommendations | Existing 1000 CMP, functioning |
| React Map 15 | RN 152 | No recommendations | Existing 600 CMP, functioning |
| React Map 15 | RN 153 | No recommendations | Existing 1000 CMP, functioning |
| React Map 15 | RN 154 | P.Eng. inspection required | Log bridge, 14m long, ravelling soft material on sides |
| React Map 15 | RN 155 | No recommendations | Existing 600 CMP, functioning |
| React Map 15 | RN 156 | No recommendations | Existing 400 rusted CMP, functioning |
| React Map 15 | RN 157 | No recommendations | Existing cross drain |
| React Map 15 | RN 158 | No recommendations | Existing 600 CMP , stream crossing |
| React Map 15 | RN 159 | No recommendations | Existing 1000 CMP, functioning |
| React Map 15 | RN 160 | No recommendations | Existing 600 CMP, functioning |
| React Map 15 | JE 272 | Clean inlet | Existing cmp inlet is infilled |
| React Map 15 | JE 271 | Clean inlet | Existing CMP |
| React Map 15 | JE 270 | Clean inlet | Existing CMP |
| React Map 15 | JE 269 | Clean inlet | Existing CMP |
| React Map 15 | JE 268 | Clean inlet and infill hole on upstream side of cmp | Existing CMP |
| React Map 15 | JE 267 | Clean inlet | Existing cmp inlet completely inilled |
| React Map 15 | JE 266 | Clean inlet | Existing CMP |
| React Map 15 | JE 265 | Clean inlet | Existing CMP |
| React Map 15, 16 | JE 264 | Add new guard log | Existing cmp upstream guard log has settled vehicles could get pulled down road edge |
| React Map 15, 16 | JE 263 | Clean inlet | Existing CMP |
| React Map 16 | JE 262 | Clean inlet | Existing CMP |
| React Map 16 | JE 261 | Clean inlet | Existing CMP |
| React Map 16 | JE 260 | Clean inlet | Existing CMP |
| React Map 16 | JE 259 | Clean inlet | Existing plastic pipe |
| React Map 16 | JE 258 | Clean inlet | Existing plastic pipe |
| React Map 16 | JE 257 | Start LPB | Cutslope is ravelling here. |
| React Map 16 | JE 256 | End LPB | More mat pushed over steep fills. Old slide here |
| React Map 16 | JE 255 | Start LPB | |

Appendix D: Road Reactivation Recommendations for Stewardson Mainline

| Road/Map # | Station | Recommendation | Comments |
|------------------|---------|--|--|
| React Map 16 | JE 254 | Clean ditch | Cutslope failure has infilled ditch water is flowing down road |
| React Map 16 | JE 253 | End LPB | Material pushed over steep fills again |
| React Map 16 | JE 252 | Clean inlet | Existing CMP |
| React Map 16 | JE 251 | Start LPB | |
| React Map 16 | JE 250 | End LPB | Material pushed over steep again. Remove and end haul |
| React Map 16 | JE 249 | Start LPB | Tc 1-2 m in from road edge along interval |
| React Map 16 | JE 248 | End LPB of material pushed over fill slope | Debris has been pushed down steep fill slope and is at risk of sliding into fish |
| React Map 16 | JE 247 | Start LPB. Move road into slope if required. Install guard log | |
| React Map 16 | JE 246 | End LPB | 7m wide fill slope failure. Debris has been pushed to the outside road edge -80% cut is 3 m high till with dr up to 30cm dbh |
| React Map 16 | JE 245 | Replace existing cmp | Broken and infilled cmp. Start of 6-7 m high till cutslope ravel I filling ditch |
| React Map 16 | JE 244 | Clean inlet | 2*800 an avulsion upstream is flowing into ditch and then pipes wedge of sediment ready to plug pipes. |
| React Map 16 | JE 243 | P.Eng. inspection required | Existing wooden bridge no guard log on downstream side |
| React Map 16 | JE 242 | No recommendations | Old fill slope failure has been repaired |
| React Map 16 | JE 241 | Replace existing cmp | 800 is ripped apart at inlet 1.5 into road |
| React Map 16 | JE 240 | Clean inlet | Existing CMP |
| React Map 16 | JE 239 | Clean inlet | Existing CMP |
| React Map 16 | JE 238 | Clean inlet | Existing CMP |
| React Map 16 | JE 237 | Clean inlet | Existing CMP |
| React Map 16 | JE 236 | Clean inlet | Existing CMP |
| React Map 16 | JE 235 | Clean inlet | Existing CMP |
| React Map 16 | JE 234 | P.Eng. inspection required | Existing wooden bridge 13 m |
| React Map 16 | JE 233 | Clean inlet | Existing CMP |
| React Map 16 | JE 232 | Clean inlet | Existing CMP |
| React Map 16, 17 | JE 231 | Clean inlet | Existing CMP |
| React Map 17 | JE 230 | Clean inlet | Existing plastic pipe |
| React Map 17 | JE 229 | Clean inlet | Existing plastic pipe |
| React Map 17 | JE 228 | Add more fill and guard log on high side | Sharp drop to ditch |
| React Map 17 | JE 227 | Clean inlet | Existing CMP |
| React Map 17 | JE 226 | P.Eng. inspection required | 6-7 m wooden bridge |

Appendix D: Road Reactivation Recommendations for Stewardson Mainline

| Road/Map # | Station | Recommendation | Comments |
|--------------|---------|----------------------------|--|
| React Map 17 | JE 225 | P.Eng. inspection required | 1*5 wbc |
| React Map 17 | JE 224 | Add cmp | Only if long term road. |
| React Map 17 | JE 223 | Clean inlet | Existing CMP |
| React Map 17 | JE 222 | Clean inlet | Existing CMP |
| React Map 17 | JE 221 | Clean inlet | Existing CMP |
| React Map 17 | JE 220 | Start LPB | Material from ditch has been pushed over steep fills |
| React Map 17 | JE 219 | End LPB | Endhaul to suitable spot |
| React Map 17 | JE 218 | Clean inlet | Existing CMP |
| React Map 17 | JE 217 | Clean inlet | Existing cmp |
| React Map 17 | JE 216 | Clean inlet | Existing plastic pipe |
| React Map 17 | JE 215 | Clean inlet | Existing CMP |
| React Map 17 | JE 214 | Clean inlet | Existing CMP |
| React Map 17 | JE 213 | Clean inlet | Existing cmp plugged water only trickling through |
| React Map 17 | JE 212 | Clean inlet | Existing CMP |
| React Map 17 | JE 211 | Clean inlet | Existing plastic pipe |
| React Map 17 | JE 210 | Clean inlet | Existing CMP |
| React Map 17 | JE 209 | Clean inlet | Existing CMP |
| React Map 17 | JE 208 | Clean inlet | Existing cmp in old wbc |
| React Map 17 | JE 207 | Clean inlet | Existing CMP |
| React Map 17 | JE 206 | Clean inlet and outlet | Existing CMP |
| React Map 17 | JE 205 | Clean inlet | Standing water at inlet. Looks plugged |
| React Map 17 | JE 204 | Clean ditch and inlet | Inlet completely infilled |
| React Map 17 | JE 203 | Add fill | 0.3 m settled area with coarse rock |
| React Map 17 | JE 202 | P.Eng. inspection required | Escalante bridge guard rails are all busted |

Appendix E: Road Reactivation Recommendations for 9501-2 Satchie Mainline

| Road/Map # | Station | Recommendation | Comments |
|--------------------------------|---------------|--|--|
| 9501-2 Satchie Mainline | | | |
| React Map 7 | JE 119 | No recommendations | Depression on high side of road water ponding. No cvt found large fill water drains down ditch |
| React Map 7 | JE 120 | Clean inlet | |
| React Map 7 | JE 121 | Clean inlet, start clean ditch | Existing CMP water on surface of road from upchain |
| React Map 7 | JE 122 | End clean ditch | Source of water down road |
| React Map 7 | JE 123 | Clean inlet | |
| React Map 7 | JE 124 | Clean inlet | |
| React Map 7, 8 | JE 127 | Clean inlet | |
| React Map 7, 8 | JE 125 | Existing CMP | Drainage from old spur runs onto ml benches below. Connect large xd to this CMP. Alternatively move CMP to camp side of spur |
| React Map 7, 8 | JE 128 | Clean inlet | |
| React Map 8 | JE 129 | No recommendations | Landing |
| React Map 8 | JE 130 | Repack, excavate if required | Hole in road at CMP |
| React Map 8 | JE 131 | Clean inlet | |
| React Map 8 | JE 132 | Requires P.Eng inspection | Existing all steel portable 9m |
| React Map 8 | JE 133 | P.Eng to include in bridge assessment | Avulsion channel from upstream feeds into ditch and then rejoins main stem. Overflows road at high flows maybe install large CMP here? Or larger bridge? |
| React Map 8 | JE 134 | Clean inlet | |
| React Map 8 | JE 135 | Install CMP | Lots of water in ditch several small draws feed this area |
| React Map 8 | JE 136 | Clean inlet | |
| React Map 8 | JE 137 | Start LPB | Settling shifting to tc. 5 m of road will remain cut is 3 m bouldery tills |
| React Map 8 | JE 138 | End LPB | Seepage part way along ensure ditch is clean and sufficiently deep |
| React Map 8 | JE 139 | Clean inlet | |
| React Map 8 | JE 140 | Start LPB | Settling shifting to tc. 5 m of road will remain cut is 4-5 m bouldery tills |
| React Map 8 | JE 141 | End LPB | No comments |
| React Map 8 | JE 142 | Start no additional spoil on fill slope, Clean inlet | |
| React Map 8 | TW 63 | End no additional spoil on fill slope, start LPB | Road prism in take, fill is steep |
| React Map 8 | TW 64 | No recommendations | Continue LPB of fills & 2m of outer rd surface, Move rd 1m into cut, fills settling, discontinuous cracks on shoulder extending p to 2 m into outer rd surface |

Appendix E: Road Reactivation Recommendations for 9501-2 Satchie Mainline

| Road/Map # | Station | Recommendation | Comments |
|-------------|---------------|---|---|
| React Map 8 | TW 66 | Add 600 CMP, start clean ditch | Water piping out of dense till |
| React Map 8 | TW 65 | Install CMP, continue LPB, clean cut slump & ditch line, EH spoil | 5m w cut slide block CMP, flow across rd, tension cracks on fill & 2 m from outer shoulder, main flow here, water piping out of dense till, needs , multi CMP |
| React Map 8 | TW 67 | End LPB of fill, end clean ditch, start brushing & ditching | LPB including shoulder 0.5-1.5m w, eh spoil, may have to move rd into ditch, Fills settling & 0.5-1m shoulder |
| React Map 8 | TW 68 | Add 600 CMP, armor outlet | 3-4 m w Ncd draw w flows, no visible CMP, no obvious draw below steep fills on 55% benched 30m below, steep fills need to be armoured |
| React Map 8 | TW 69 | No recommendations | Existing functioning 800CMP, no str |
| React Map 8 | TW 70 | No recommendations | Existing 600 cm, intake fine, outlet is armoured, slopes decrease |
| React Map 8 | TW 71 | Add 600 CMP | Seepage Ncd |
| React Map 8 | TW 72 | Install 600 CMP, clean ditch | 3 m by 1m draw w 0.75m g ch, no visible CMP but ditch line infilled, is down chain surface flow, no slide concern |
| React Map 8 | TW 73 | Clean ditch | Double 600 CMPs, ditch infilled & partially blocking intakes |
| React Map 8 | TW 74 | Add 600 CMP | Wet draw no CMP |
| React Map 8 | TW 75 | No recommendations | Existing 600 CMP |
| React Map 8 | TW 76 | End brushing & ditching, start excavate outer shoulder & fills, remove fines & wood, repack | No fill or cut instability, here @76 start settling fill |
| React Map 8 | TW 77 | No recommendations | Continue excavate and repack outer 2m of road, Settling g now 2 m of outer rd surface, including shoulder |
| React Map 8 | TW 79 | No recommendations | Continue excavate and repack outer 2m of road, Fill & outer 2 m rd surface settled , existing CMP functioning , infilled ditch causing settling |
| React Map 8 | TW 80 | No recommendations | Continue excavate and repack outer 2m of road |
| React Map 8 | TW 81 | Start LPB, end excavate and repack outer 2m of road | Settling along shoulder extending cracks 0.5-2 m into outer rd surface |
| React Map 8 | JE 186 | End LPB | Tension cracks 0.5-2 m from road edge. 5 m of road will remain |
| React Map 8 | JE 185 | Clean inlet | |
| React Map 8 | JE 184 | Clean inlet | |
| React Map 8 | JE 183 | Clean inlet | |
| React Map 8 | JE 182 | Clean inlet | |
| React Map 8 | JE 181 | Clean inlet | |

Appendix E: Road Reactivation Recommendations for 9501-2 Satchie Mainline

| Road/Map # | Station | Recommendation | Comments |
|-------------|---------|--------------------------------------|--|
| React Map 8 | JE 180 | No recommendations | Existing wooden bridge. Has been assessed by OEL |
| React Map 9 | JE 179 | Clean inlet | |
| React Map 9 | JE 178 | Clean inlet | |
| React Map 9 | JE 177 | Clean inlet | |
| React Map 9 | JE 176 | Clean inlet | |
| React Map 9 | JE 175 | Clean inlet | |
| React Map 9 | JE 174 | Clean inlet | |
| React Map 9 | JE 173 | No recommendations | Existing wooden bridge. Has been assessed by OEL |
| React Map 9 | JE 172 | No recommendations | Existing reverse WB into ditch berm on outside road edge |
| React Map 9 | JE 171 | Clean ditch | Clean inlet |
| React Map 9 | JE 170 | No recommendations | Erosion of road surface will be fixed once ditches are clean |
| React Map 9 | JE 169 | No recommendations | Existing WBC has been assessed by OEL |
| React Map 9 | JE 168 | Clean inlet | |
| React Map 9 | JE 167 | Repack road at inlet and clean inlet | Drainage down road flows into ditch and through CMP. Has eroded the road edge at inlet |
| React Map 9 | JE 166 | Add CMP | Water is eroding road below here with infilled ditch |
| React Map 9 | JE 165 | Clean inlet | |
| React Map 9 | JE 164 | Clean inlet | |
| React Map 9 | JE 163 | Clean ditch | Water down road again. Will be fixed with clean ditch |
| React Map 9 | JE 162 | Clean inlet | |
| React Map 9 | JE 161 | Clean inlet | |
| React Map 9 | JE 160 | Add CMP | Could be a pipe here already? |
| React Map 9 | JE 159 | Clean inlet | outlet CMP may need replacement, water leaves road and flows into draw on low side |
| React Map 9 | JE 158 | Clean ditch resurface road | Ditch is infilled with water down road cuts are dense block rubble Boulder sand silt till >4 m this will require maintenance |
| React Map 9 | JE 157 | Add CMP | Existing WB |
| React Map 9 | JE 156 | Clean inlet | |
| React Map 9 | JE 155 | Start clean road and ditch | Just in ditch for most of interval |
| React Map 9 | JE 154 | Clean inlet if existing | Possible pipe little draw |
| React Map 9 | JE 153 | End clean road continue clean ditch | Boulders and cobbles have infill ditch from cutslope one 0.5-1 m Boulder on road |
| React Map 9 | JE 152 | Retain WB | Existing WB |
| React Map 9 | JE 151 | Clean inlet | |
| React Map 9 | JE 150 | No recommendations | Existing WBC has been inspected |
| React Map 9 | JE 149 | Clean ditch | Few 0.5 m boulders in ditch from cutslope will get remove when ditches are cleaned |
| React Map 9 | JE 148 | No recommendations | French drain? Seems to be working ok |
| React Map 9 | JE 147 | Clean inlet | |
| React Map 9 | JE 146 | Clean inlet if existing | Possible buried pipe |

Appendix E: Road Reactivation Recommendations for 9501-2 Satchie Mainline

| Road/Map # | Station | Recommendation | Comments |
|-------------|---------------|--------------------|--|
| React Map 9 | JE 145 | Clean inlet | |
| React Map 9 | JE 144 | Pull wooden bridge | If not opening beyond pull wooden bridge 8 m |
| React Map 9 | JE 143 | No recommendations | Outside of scope but tension cracks. Would deposit into upper bowl |

APPENDIX F

**Rockfall Hazard Assessment
Zuciarte Main – 5.0 km
Zuciarte Channel, B.C.**

Prepared for:
Zoltan Schafer, RPF
MaMook Natural Resources

Courtenay Office

#201 – 780 Grant Avenue
Courtenay, BC
V9N 2T3
Tel: 778-647-5643
Fax 1-866-235-6943

July 29, 2024
File: 988-5-4

EGBC PERMIT TO PRACTICE: 1002678

Table of Contents

| | | |
|-----|--------------------------------------|---|
| 1.0 | Introduction | 3 |
| 2.0 | Office and Field Review | 4 |
| 3.0 | Geotechnical Site Assessment | 4 |
| 4.0 | Discussion and Recommendations | 5 |
| 6.0 | Closure | 6 |

Attached

Photo Plates
Work Safe Procedures

1.0 Introduction

At the request of MaMook Natural Resources (MaMook), Onsite Engineering Ltd. (OEL) was retained to carry out a rockfall assessment of and an existing cut slope at 5.0 km on Zuciarte main, near Zuciarte Channel, 3.2 km southwest of Mooyah Bay, Vancouver Island, B.C., (the "Subject Site"). The field work was completed on July 17th, 2024, by Jon Kroon, P.Geo., and Liam Giblin, GIT, of OEL.

Access along Zuciarte Mainline is blocked at 5.0 km due to rockfall debris from a cut slope failure. The date of the failure is unknown. The purpose of this assessment is to determine if access can be gained for reactivation and deactivation works planned in the Escalante and Stewardson Camp areas and to provide safe work procedures for works around the failure site. A professional assessment has been completed to mitigate the remaining rockfall hazard. Planned operations include the excavation of the existing rock debris and access for pickups, a rock truck, a low bed, and an excavator for road works beyond; no hauling is currently planned along Zuciarte Main.

This report discusses the findings of the field assessment and the corresponding slope stability review conducted. Recommendations to mitigate risk to workers from the identified potential slope instability are included below. The rockfall location and associated hazard area is included on road deactivation/reactivation maps for the Stewardson Camp area (sent as a separate document).

A previous assessment of Zuciarte Mainline was completed for International Forest Products in 2014 by the author that assessed rockfall hazards at this location. This specific cut face was identified as having the potential to detach and deposit on the mainline, blocking access. The estimated volume of unstable rock was 85 m³. Additional sites were also identified as having potential for rock fall of varying volumes, including 0.0 km, 2.8 km, 8.1 km, 8.7 km, 9.2 km, 10.0 km, 11.2 km, 12.2 km.

This assessment has been prepared in accordance with generally accepted geotechnical practices in British Columbia.

General observations are made on the existing slope gradients, fracturing, weathering and general stability of the rock outcrop. Variations along the cut face (even over short distances) are inherent and are a function of natural processes. OEL does not represent or warrant that the conditions listed in the report are exact and that variations along the cut face do exist. An estimate of the likelihood of a specific hazardous rockfall or landslide reaching the subject property is provided.




Figure 1: Location Map

2.0 Office and Field Review

Prior to and following the field assessment the following materials were reviewed:

- BC Digital Geology Mapping – compilations of the bedrock geology of BC obtained from <https://www.geosciencebc.com/>.
- Aztec Geoscience report titled “Cutslope Hazards – Zuchiarte and Escalante Mainlines and Branch Z1” dated 15 October, 2014

The field review consisted of a walk through using a compass, clinometer, range finder, and an iPad with digital applications including Avenza Maps Pro. Measurements contained in this report reflect the precision and accuracy of these tools.

3.0 Geotechnical Site Assessment

The Subject Site is characterized by a road cut slope excavation into bedrock overlain by a thin (<1 m) layer of till soil. The bedrock cut reaches ~12 m high and is composed of a moderately fractured metamorphic rock mass that is thought to belong to the Paleozoic to Jurassic, Westcoast Crystalline Complex. The bedrock has widely spaced fractures that form large potentially unstable blocks. Multiple fractures are visible, but no obvious dominant joint set is apparent, and fractures are largely discontinuous. One fracture appears to be dipping downslope toward the road and a second prevalent fracture appears to be roughly vertical.

The road was approximately 5 m wide at the failure site with road grades generally level. A small ditch exists but it is insufficient to capture rockfall. Slopes below the road are steep reaching -100% and the road appears to be constructed with a full bench cut. No stream or seepage was observed at the site.

The recent rockfall event at the Subject Site initiated from the upper cut face and mostly deposited on the road surface. One block was observed on slope below the road. The estimated volume of rock is 30 m³ with the largest block estimated to be 10 m³ and a 5 m³ block below the road. An estimated 85 m³ of rock was considered potentially loose during the 2014 assessment leaving an approximately 55 m³ potentially loose rock mass remaining on the cut slope.

4.0 Discussion and Recommendations

Under the current state, the perched and potentially unstable remaining rock mass has a high likelihood of failure within the expected lifetime of the road. Should the rock mass fail, an estimated volume range of 35 to 70 m³ of rock would be deposited on the road blocking access. Minor material may over top the road but is not expected to reach the ocean. Approximately 20 m up-chain additional material was observed that has the potential to detach and deposit on the road surface.

Ideally the full hazardous rock mass should be removed, which would eliminate the hazard entirely. Removing this volume of rock may be uneconomical and technically challenging; therefore, leaving the mass in place is considered as a second viable option, *as long no additional cutting or further disturbance to the cut slope is performed at the rock mass location*. Should any cutting of the toe of the rock face be carried out, the likelihood of failure and related hazard is considered **unacceptable**, and the Subject Site will need to be professionally reassessed by a senior engineer or geoscientist.

The following recommendations should be implemented to reduce the likelihood of hazardous rockfall impacting personnel working at the Subject Site:

1. Drill and blast large pieces of the rockfall debris located on the road and end haul material to a suitable spoil site.
2. Follow Safe Work Procedure for operations of removal of rock material.
3. If hazardous rock is not removed, install rockfall hazard/no stopping signage from 5.0 to 5.1 km

The above recommendations are provided based on the site conditions as of July 17, 2024. Any change in site conditions (either due to additional work, or due to natural processes) should trigger further review.

6.0 Closure

This assessment has been carried out in accordance with generally accepted geotechnical practices. Conclusions and recommendations presented herein are based on visual site inspections. Assessments of rockfall hazards are based on interpretation of surface features; actual ground conditions may vary from those inferred. Should the bedrock conditions encountered differ from those outlined in this report; OEL should be contacted so that the recommendations contained in this report can be reviewed.

Sincerely,
Onsite Engineering Ltd.

Jon Kroon, P.Geo.
Senior Geoscientist

Attached:

1. Photo Plates
2. Safe Work Procedures



1a



1b

Photo 1a:

Conditions of rock face in 2014 during the rock slope assessment by Aztec Geoscience showing block detachment in upper right-hand corner (orange outline). Taken October 15, 2014

Photo 1b:

Conditions of rockface during the 2024 assessment, showing potential additional rockfall (red outline). Taken July 17, 2024



Photo 2:
Deep soil filled fracture noted on 2014 site visit, showing possible widening through root growth. Taken July 17, 2024



Photo 3:
View looking down-chain. Taken July 17, 2024



Photo 3:
View looking up-chain.
Taken July 17, 2024



Photo 4:
Potential additional
rock fall site at 5.2 km.

A SAFE WORK PROCEDURE FOR Zuciarte Main 5.0 km

The purpose of these instructions is to provide guidance on safe work procedures for the clearing of rock at the 5.0 km rockfall site on Zuciarte Main. These Safe Work Procedures are for the clearing of blocks from the site only.

SAFE WORK PROCEDURE

- 1.0 All workers on site must sign off on the prime contractor's worksite sheet that they have read and understood these instructions (i.e. during a tailboard meeting).
- 2.0 A copy of these procedures must be available on site for ALL workers at ALL times.
- 3.0 All workers must have high visibility clothing and hard hats.
- 4.0 No worker shall stand or pass between any equipment and the cutslope.
- 5.0 The times that workers are on or below the road outside of a machine must be limited to necessary work only. When work is required in the area, minimize time spent with your back to the slope. **NO WORKERS ARE PERMITTED OUTSIDE MACHINES BELOW THE LOOSE COLLUVIAL SLOPES.**
- 6.0 When working below the site, all workers and machinery must have a clear escape path. The escape path must be made clear to all workers in the work area.
- 7.0 Working at the toe of the slope is prohibited unless operating machinery.
- 8.0 Whenever a worker (or workers) are working outside of their machines, another worker not involved in the works, must act as a spotter for raveling/falling materials. It is expected that the only work outside machines will be to load explosives in the holes following drilling.
- 9.0 Special care shall be considered during heavy rainfall. Follow the reduce rainfall shutdown guidelines as outlined below. Shutdown for the site if drainage systems are overflowing or surface sediments are saturated. Restart work after 24 hours from the cessation of rainfall and inspect the slope for loose material prior to entering the area.

| Reduce Rainfall Shutdown Guidelines | Time Period | | | |
|-------------------------------------|---|-------|--------|--------|
| | At start or before end of shift (12-hr) | 24-hr | 48-hr | 72-hr |
| Standard Shutdown Levels | 50 mm | 80 mm | 120 mm | 160 mm |
| Snow present Shutdown Levels | 30 mm | 50 mm | 80 mm | 110 mm |

- 10.0 If any changed conditions are encountered or any rock movement is noted, all work must stop immediately and the QRP must be called to give further instruction.
- 11.0 A spotter is required while drilling for overall movement and upslope rockfall.